

7th Generation Intel® Processor Family

Specification Update

Supporting 7th Generation Intel® Core™ Processor Families based on Y/U/H/S-Processor Line, Y/U With iHDCP2.2-Processor Line and Intel® Pentium® Processors and Intel® Celeron® Processor

March 2017

Revision 005



You may not use or facilitate the use of this document in connection with any infringement or other legal analysis concerning Intel products described herein. You agree to grant Intel a non-exclusive, royalty-free license to any patent claim thereafter drafted which includes subject matter disclosed herein.

No license (express or implied, by estoppel or otherwise) to any intellectual property rights is granted by this document.

Intel technologies' features and benefits depend on system configuration and may require enabled hardware, software or service activation. Learn more at Intel.com, or from the OEM or retailer.

No computer system can be absolutely secure. Intel does not assume any liability for lost or stolen data or systems or any damages resulting from such losses.

The products described may contain design defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.

Intel disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade.

Intel technologies' features and benefits depend on system configuration and may require enabled hardware, software or service activation. Learn more at intel.com, or from the OEM or retailer.

All information provided here is subject to change without notice. Contact your Intel representative to obtain the latest Intel product specifications and roadmaps.

Copies of documents which have an order number and are referenced in this document may be obtained by calling 1-800-548-4725 or visit www.intel.com/design/literature.htm.

Intel, the Intel Core, Pentium, Celeron, and the Intel logo are trademarks of Intel Corporation in the U.S. and/or other countries.

*Other names and brands may be claimed as the property of others.

Copyright © 2016-2017, Intel Corporation. All Rights Reserved.



Contents

| | |
|-----------------------------------|----|
| Revision History..... | 4 |
| Preface..... | 5 |
| Identification Information | 7 |
| Summary Tables of Changes | 15 |
| Errata..... | 23 |
| Specification Changes | 49 |
| Specification Clarifications..... | 50 |
| Documentation Changes | 51 |



Revision History

| Revision | Description | Date |
|----------|---|---------------|
| 001 | Initial release | August 2016 |
| 002 | <ul style="list-style-type: none">• Errata<ul style="list-style-type: none">— Added errata KBL068-078— Updated erratum KBL062— Fixed erratum KBL063 | November 2016 |
| 003 | <ul style="list-style-type: none">• Added SKUs Y/U w/iHDCP2.2, S/H-Processor lines• Added Table 2, S/H-Processor Lines Component Identification• Identification Information<ul style="list-style-type: none">— Added Table 4, Y-Processor Line With iHDCP2.2— Added Table 6, U-Processor Line With iHDCP2.2— Added Figure 3, S-Processor Line LGA Top-Side Markings— Added Table 7, S-Processor Line— Added Figure 4, H-Processor Line BGA Top-Side Markings— Added Table 8, H-Processor Line• Errata<ul style="list-style-type: none">— Updated Table 13, Errata Summary Table— Added errata KBL079-083 | January 2017 |
| 004 | <ul style="list-style-type: none">• Identification Information<ul style="list-style-type: none">— Updated Table 4, Y-Processor Line With iHDCP2.2• Errata<ul style="list-style-type: none">— Updated Table 13, Errata Summary Table. Added J-1 stepping— Updated KBL080— Added errata KBL084-091 | February 2017 |
| 005 | <ul style="list-style-type: none">• Errata<ul style="list-style-type: none">— Added errata KBL092-094 | March 2017 |



Preface

This document is an update to the specifications contained in the documents listed in the following Affected Documents/Related Documents table. It is a compilation of device and document errata and specification clarifications and changes, and is intended for hardware system manufacturers and for software developers of applications, operating system, and tools.

Information types defined in the Nomenclature section of this document are consolidated into this update document and are no longer published in other documents. This document may also contain information that has not been previously published.

Affected Documents

| Document Title | Document Number/Location |
|---|--------------------------|
| 7th Generation Intel® Processor Families for U/Y Platforms Datasheet, Volume 1 of 2 | 334661 |
| 7th Generation Intel® Processor Families for U/Y Platforms Datasheet, Volume 2 of 2 | 334662 |

Related Documents

| Document Title | Document Number/Location |
|---|---|
| <i>AP-485, Intel® Processor Identification and the CPUID Instruction</i> | http://www.intel.com/design/processor/ap/notes/241618.htm |
| Intel® 64 and IA-32 Architectures Software Developer’s Manual, Volume 1: Basic Architecture Intel® 64 and IA-32 Architectures Software Developer’s Manual, Volume 2A: Instruction Set Reference Manual A-M Intel® 64 and IA-32 Architectures Software Developer’s Manual, Volume 2B: Instruction Set Reference Manual N-Z Intel® 64 and IA-32 Architectures Software Developer’s Manual, Volume 3A: System Programming Guide Intel® 64 and IA-32 Architectures Software Developer’s Manual, Volume 3B: System Programming Guide Intel® 64 and IA-32 Intel Architecture Optimization Reference Manual | http://www.intel.com/products/processor/manuals/index.htm |
| Intel® 64 and IA-32 Architectures Software Developer’s Manual Documentation Changes | http://www.intel.com/content/www/us/en/processors/architectures-software-developer-manuals.html |
| ACPI Specifications | www.acpi.info |



Nomenclature

Errata are design defects or errors. Errata may cause the processor's behavior to deviate from published specifications. Hardware and software designed to be used with any given stepping must assume that all errata documented for that stepping are present on all devices.

Specification Changes are modifications to the current published specifications. These changes will be incorporated in the next release of the specifications.

Specification Clarifications describe a specification in greater detail or further highlight a specification's impact to a complex design situation. These clarifications will be incorporated in the next release of the specifications.

Documentation Changes include typos, errors, or omissions from the current published specifications. These changes will be incorporated in the next release of the specifications.

Note: Errata remain in the specification update throughout the product's lifecycle, or until a particular stepping is no longer commercially available. Under these circumstances, errata removed from the specification update are archived and available upon request. Specification changes, specification clarifications, and documentation changes are removed from the specification update when the appropriate changes are made to the appropriate product specification or user documentation (datasheets, manuals, etc.).

§



Identification Information

Component Identification via Programming Interface

The processor stepping can be identified by the following register contents:

Table 1. Y/U-Processor Lines Component Identification

| Reserved | Extended Family | Extended Model | Reserved | Processor Type | Family Code | Model Number | Stepping ID |
|----------|-----------------|----------------|----------|----------------|-------------|--------------|-------------|
| 31:28 | 27:20 | 19:16 | 15:14 | 13:12 | 11:8 | 7:4 | 3:0 |
| | 0000000b | 1000b | | 00b | 0110b | 1110b | xxxxb |

Table 2. S/H-Processor Lines Component Identification

| Reserved | Extended Family | Extended Model | Reserved | Processor Type | Family Code | Model Number | Stepping ID |
|----------|-----------------|----------------|----------|----------------|-------------|--------------|-------------|
| 31:28 | 27:20 | 19:16 | 15:14 | 13:12 | 11:8 | 7:4 | 3:0 |
| | 0000000b | 1001b | | 00b | 0110b | 1110b | xxxxb |

Notes:


1. The Extended Family, Bits [27:20] are used in conjunction with the Family Code, specified in Bits [11:8], to indicate whether the processor belongs to the Intel386™, Intel486™, Pentium®, Pentium 4, or Intel® Core™ processor family.
2. The Extended Model, Bits [19:16] in conjunction with the Model Number, specified in Bits [7:4], are used to identify the model of the processor within the processor's family.
3. The Family Code corresponds to Bits [11:8] of the EDX register after RESET, Bits [11:8] of the EAX register after the CPUID instruction is executed with a 1 in the EAX register, and the generation field of the Device ID register accessible through Boundary Scan.
4. The Model Number corresponds to Bits [7:4] of the EDX register after RESET, Bits [7:4] of the EAX register after the CPUID instruction is executed with a 1 in the EAX register, and the model field of the Device ID register accessible through Boundary Scan.
5. The Stepping ID in Bits [3:0] indicates the revision number of that model. See Table 1 for the processor stepping ID number in the CPUID information.
6. Please refer to Kaby Lake Processor BIOS Writers Guide for additional information. When EAX is initialized to a value of '1', the CPUID instruction returns the Extended Family, Extended Model, Processor Type, Family Code, Model Number and Stepping ID value in the EAX register. Note that the EDX processor signature value after reset is equivalent to the processor signature output value in the EAX register.

Cache and TLB descriptor parameters are provided in the EAX, EBX, ECX and EDX registers after the CPUID instruction is executed with a 2 in the EAX register.



Component Marking Information

Figure 1. Y-Processor Line BGA Top-Side Markings



Pin Count: 1515

Package Size: 20 mm x 16.5 mm

Production (SSPEC):

GRP1LINE1: FPOxxxxSSPEC
GRP2LINE1 (G2L1): Intel logo
GRP3LINE1 (G3L1): {eX}



Table 3. Y -Processor Line


| S-Spec # | Processor Number | Step-ping | Cache Size | Func-tional Core | Processor Graphics Cores | Processor Graphics Freq. | Processor Graphics Maximum Dynamic Freq. | LPDDR3 Mem. (MT/s) | Core Freq. | Turbo 1 Core Freq. Rate | Thermal Design Power | Slot / Socket Type |
|----------|------------------|-----------|------------|------------------|--------------------------|--------------------------|--|--------------------|------------|-------------------------|----------------------|--------------------|
| R2ZT | I7-7Y75 | H-0 | 4 MB | 2 | 2 | 0.3 GHz | 1.05 GHz | 1866 | 1.3 GHz | 3.6 GHz | 4.5 W | BGA1515 |
| R2ZX | I5-7Y54 | H-0 | 4 MB | 2 | 2 | 0.3 GHz | 0.95 GHz | 1866 | 1.2 GHz | 3.2 GHz | 4.5 W | BGA1515 |
| R2ZY | M3-7Y30 | H-0 | 4 MB | 2 | 2 | 0.3 GHz | 0.9 GHz | 1866 | 1 GHz | 2.6 GHz | 4.5 W | BGA1515 |

Table 4. Y-Processor Line With iHDCP2.2

| S-Spec # | Processor Number | Step-ping | Cache Size | Func-tional Core | Processor Graphics Cores | Processor Graphics Freq. | Processor Graphics Maximum Dynamic Freq. | LPDDR3 Mem. (MT/s) | Core Freq. | Turbo 1 Core Freq. Rate | Thermal Design Power | Slot / Socket Type |
|----------|------------------|-----------|------------|------------------|--------------------------|--------------------------|--|--------------------|------------|-------------------------|----------------------|--------------------|
| R33X | I7-7Y75 | H-0 | 4 MB | 2 | 2 | 0.3 GHz | 1.05 GHz | 1866 | 1.3 GHz | 3.6 GHz | 4.5 W | BGA1515 |
| R33Y | I5-7Y57 | H-0 | 4 MB | 2 | 2 | 0.3 GHz | 0.95 GHz | 1866 | 1.2 GHz | 3.3 GHz | 4.5 W | BGA1515 |
| R345 | I5-7Y54 | H-0 | 4 MB | 2 | 2 | 0.3 GHz | 0.95 GHz | 1866 | 1.2 GHz | 3.2 GHz | 4.5 W | BGA1515 |
| R346 | M3-7Y32 | H-0 | 4 MB | 2 | 2 | 0.3 GHz | 0.9 GHz | 1866 | 1.1 GHz | 3 GHz | 4.5 W | BGA1515 |
| R347 | M3-7Y30 | H-0 | 4 MB | 2 | 2 | 0.3 GHz | 0.9 GHz | 1866 | 1 GHz | 2.6 GHz | 4.5 W | BGA1515 |
| R34B | Pentium 4410Y | H-0 | 2 MB | 2 | 2 | 0.3 GHz | 0.85 GHz | 1866 | 1.5 GHz | 1.5 GHz | 6 W | BGA1515 |
| R34E | Celeron 3965Y | H-0 | 2 MB | 2 | 2 | 0.3 GHz | 0.85 GHz | 1866 | 1.3 GHz | 1.3 GHz | 6 W | BGA1515 |



Figure 2. U-Processor Line BGA Top-Side Markings



Pin Count: 1356

Package Size: 42 mm x 24 mm

Production (SSPEC):

GRP1LINE1: FPOxxxxxSSPEC
 GRP2LINE1 (G2L1): {eX}
 GRP3LINE1 (G3L1): Intel logo

Table 5. U -Processor Line

| S-Spec # | Processor Number | Step-ping | Cache Size | Func-tional Core | Processor Graphics Cores | Processor Graphics Freq. | Processor Graphics Maximum Dynamic Freq. | DDR3L Mem. (MT/s) | LPDDR3 Mem. (MT/s) | DDR4 Mem. (MT/s) | Core Freq. | Turbo 1 Core Freq. Rate | Thermal Design Power | Slot / Socket Type |
|----------|------------------|-----------|------------|------------------|--------------------------|--------------------------|--|-------------------|--------------------|------------------|------------|-------------------------|----------------------|--------------------|
| R2ZU | I5-7200U | H-0 | 3 MB | 2 | 2 | 0.3 GHz | 1 GHz | 1600 | 1866 | 2133 | 2.5 GHz | 3.1 GHz | 15 W | BGA1356 |
| R2ZV | I7-7500U | H-0 | 4 MB | 2 | 2 | 0.3 GHz | 1.05 GHz | 1600 | 1866 | 2133 | 2.7 GHz | 3.5 GHz | 15 W | BGA1356 |
| R2ZW | I3-7100U | H-0 | 3 MB | 2 | 2 | 0.3 GHz | 1 GHz | 1600 | 1866 | 2133 | 2.4 GHz | 2.4 GHz | 15 W | BGA1356 |




Table 6. U-Processor Line With iHDCP2.2

| S-Spec # | Processor Number | Stepping | Cache Size | Functional Core | Processor Graphics Cores | Processor Graphics Freq. | Processor Graphics Maximum Dynamic Freq. | DDR3L Mem. (MT/s) | LPDDR3 Mem. (MT/s) | DDR4 Mem. (MT/s) | Core Freq. | Turbo 1 Core Freq. Rate | Thermal Design Power | Slot / Socket Type |
|----------|------------------|----------|------------|-----------------|--------------------------|--------------------------|--|-------------------|--------------------|------------------|------------|-------------------------|----------------------|--------------------|
| R33Z | I7-7600U | H-0 | 4 MB | 2 | 2 | 0.3 GHz | 1.15 GHz | 1600 | 1866 | 2133 | 2.8 GHz | 3.9 GHz | 15 W | BGA1356 |
| R340 | I5-7300U | H-0 | 3 MB | 2 | 2 | 0.3 GHz | 1.1 GHz | 1600 | 1866 | 2133 | 2.6 GHz | 3.5 GHz | 15 W | BGA1356 |
| R341 | I7-7500U | H-0 | 4 MB | 2 | 2 | 0.3 GHz | 1.05 GHz | 1600 | 1866 | 2133 | 2.7 GHz | 3.5 GHz | 15 W | BGA1356 |
| R342 | I5-7200U | H-0 | 3 MB | 2 | 2 | 0.3 GHz | 1 GHz | 1600 | 1866 | 2133 | 2.5 GHz | 3.1 GHz | 15 W | BGA1356 |
| R343 | I3-7100U | H-0 | 3 MB | 2 | 2 | 0.3 GHz | 1 GHz | 1600 | 1866 | 2133 | 2.4 GHz | 2.4 GHz | 15 W | BGA1356 |
| R348 | Pentium 4415U | H-0 | 2 MB | 2 | 1 | 0.3 GHz | 0.95 GHz | 1600 | 1866 | 2133 | 2.3 GHz | 2.3 GHz | 15 W | BGA1356 |
| R349 | Celeron 3865U | H-0 | 2 MB | 2 | 1 | 0.3 GHz | 0.9 GHz | 1600 | 1866 | 2133 | 1.8 GHz | 1.8 GHz | 15 W | BGA1356 |
| R34A | Celeron 3965U | H-0 | 2 MB | 2 | 1 | 0.3 GHz | 0.9 GHz | 1600 | 1866 | 2133 | 2.2 GHz | 2.2 GHz | 15 W | BGA1356 |
| R360 | I5-7287U | J-1 | 4 MB | 2 | 3 | 0.3 GHz | 1.1 GHz | 1600 | 1866 | 2133 | 3.3 GHz | 3.7 GHz | 28 W | BGA1356 |
| R361 | I3-7167U | J-1 | 3 MB | 2 | 3 | 0.3 GHz | 1 GHz | 1600 | 1866 | 2133 | 2.8 GHz | 2.8 GHz | 28 W | BGA1356 |
| R362 | I5-7267U | J-1 | 4 MB | 2 | 3 | 0.3 GHz | 1.05 GHz | 1600 | 1866 | 2133 | 3.1 GHz | 3.5 GHz | 28 W | BGA1356 |
| R363 | I5-7260U | J-1 | 4 MB | 2 | 3 | 0.3 GHz | 0.95 GHz | 1600 | 1866 | 2133 | 2.2 GHz | 3.4 GHz | 15 W | BGA1356 |
| R365 | I5-7360U | J-1 | 4 MB | 2 | 3 | 0.3 GHz | 1 GHz | 1600 | 1866 | 2133 | 2.3 GHz | 3.6 GHz | 15 W | BGA1356 |
| R366 | I7-7560U | J-1 | 4 MB | 2 | 3 | 0.3 GHz | 1.05 GHz | 1600 | 1866 | 2133 | 2.4 GHz | 3.8 GHz | 15 W | BGA1356 |
| R367 | I7-7567U | J-1 | 4 MB | 2 | 3 | 0.3 GHz | 1.15 GHz | 1600 | 1866 | 2133 | 3.5 GHz | 4 GHz | 28 W | BGA1356 |
| R368 | I7-7660U | J-1 | 4 MB | 2 | 3 | 0.3 GHz | 1.1 GHz | 1600 | 1866 | 2133 | 2.5 GHz | 4 GHz | 15 W | BGA1356 |



Figure 3. S-Processor Line LGA Top-Side Markings



Pin Count: 1151

Package Size: 37.5 mm x 37.5 mm

Production (SSPEC):


| | |
|------------|-------------|
| GRP1LINE1: | Intel logo |
| GRP1LINE2: | BRAND |
| GRP1LINE3: | PROC# |
| GRP1LINE4: | SSPEC SPEED |
| GRP1LINE5: | {FPO} {eX} |



Table 7. S-Processor Line

| S-Spec # | Processor Number | Stepping | Cache Size | Functional Core | Processor Graphics Cores | Processor Graphics Freq. | Processor Graphics Maximum Dynamic Freq. | DDR4 Mem. (MT/s) | DDR3L Mem. (MT/s) | Core Freq. | Turbo 1 Core Freq. Rate | Thermal Design Power | Slot / Socket Type |
|----------|------------------|----------|------------|-----------------|--------------------------|--------------------------|--|------------------|-------------------|------------|-------------------------|----------------------|--------------------|
| R32V | I5-7600K | B-0 | 6 MB | 4 | 2 | 0.35 GHz | 1.15 GHz | 2400 | 1600 | 3.8 GHz | 4.2 GHz | 91 W | LGA1151 |
| R32W | I5-7400 | B-0 | 6 MB | 4 | 2 | 0.35 GHz | 1 GHz | 2400 | 1600 | 3 GHz | 3.5 GHz | 65 W | LGA1151 |
| R332 | I5-7400T | B-0 | 6 MB | 4 | 2 | 0.35 GHz | 1 GHz | 2400 | 1600 | 2.4 GHz | 3 GHz | 35 W | LGA1151 |
| R334 | I5-7600 | B-0 | 6 MB | 4 | 2 | 0.35 GHz | 1.15 GHz | 2400 | 1600 | 3.5 GHz | 4.1 GHz | 65 W | LGA1151 |
| R335 | I5-7500 | B-0 | 6 MB | 4 | 2 | 0.35 GHz | 1.1 GHz | 2400 | 1600 | 3.4 GHz | 3.8 GHz | 65 W | LGA1151 |
| R336 | I5-7600T | B-0 | 6 MB | 4 | 2 | 0.35 GHz | 1.1 GHz | 2400 | 1600 | 2.8 GHz | 3.7 GHz | 35 W | LGA1151 |
| R337 | I5-7500T | B-0 | 6 MB | 4 | 2 | 0.35 GHz | 1.1 GHz | 2400 | 1600 | 2.7 GHz | 3.3 GHz | 35 W | LGA1151 |
| R338 | I7-7700 | B-0 | 8 MB | 4 | 2 | 0.35 GHz | 1.15 GHz | 2400 | 1600 | 3.6 GHz | 4.2 GHz | 65 W | LGA1151 |
| R339 | I7-7700T | B-0 | 8 MB | 4 | 2 | 0.35 GHz | 1.15 GHz | 2400 | 1600 | 2.9 GHz | 3.8 GHz | 35 W | LGA1151 |
| R33A | I7-7700K | B-0 | 8 MB | 4 | 2 | 0.35 GHz | 1.15 GHz | 2400 | 1600 | 4.2 GHz | 4.5 GHz | 91 W | LGA1151 |

Figure 4. H-Processor Line BGA Top-Side Markings





Pin Count: 1440

Package Size: 42 mm x 28 mm

Production (SSPEC):

GRP1LINE1 (G1L1): {eX}
 GRP2LINE1: FPOxxxxSSPEC
 GRP3LINE1 (G3L1): Intel logo

Table 8. H-Processor Line

| S-Spec # | Processor Number | Step-ping | Cache Size | Func-tional Core | Processor Graphics Cores | Processor Graphics Freq. | Processor Graphics Maximum Dynamic Freq. (GHz) | DDR4 Mem. (MT/s) | LPDDR3 Mem. (MT/s) | Core Freq. | Turbo 1 Core Freq. Rate | Thermal Design Power | Slot / Socket Type |
|----------|------------------|-----------|------------|------------------|--------------------------|--------------------------|--|------------------|--------------------|------------|-------------------------|----------------------|--------------------|
| R32H | E3-1535MV6 | B-0 | 8 MB | 4 | 2 | 0.35 GHz | 1.1 GHz | 2400 | 2133 | 3.1 GHz | 4.2 GHz | 45 W | BGA1440 |
| R32K | E3-1505MV6 | B-0 | 8 MB | 4 | 2 | 0.35 GHz | 1.1 GHz | 2400 | 2133 | 3 GHz | 4 GHz | 45 W | BGA1440 |
| R32L | I7-7920HQ | B-0 | 8 MB | 4 | 2 | 0.35 GHz | 1.1 GHz | 2400 | 2133 | 3.1 GHz | 4.1 GHz | 45 W | BGA1440 |
| R32N | I7-7820HQ | B-0 | 8 MB | 4 | 2 | 0.35 GHz | 1.1 GHz | 2400 | 2133 | 2.9 GHz | 3.9 GHz | 45 W | BGA1440 |
| R32P | I7-7820HK | B-0 | 8 MB | 4 | 2 | 0.35 GHz | 1.1 GHz | 2400 | 2133 | 2.9 GHz | 3.9 GHz | 45 W | BGA1440 |
| R32Q | I7-7700HQ | B-0 | 6 MB | 4 | 2 | 0.35 GHz | 1.1 GHz | 2400 | 2133 | 2.8 GHz | 3.8 GHz | 45 W | BGA1440 |
| R32R | I5-7440HQ | B-0 | 6 MB | 4 | 2 | 0.35 GHz | 1 GHz | 2400 | 2133 | 2.8 GHz | 3.8 GHz | 45 W | BGA1440 |
| R32S | I5-7300HQ | B-0 | 6 MB | 4 | 2 | 0.35 GHz | 1 GHz | 2400 | 2133 | 2.5 GHz | 3.5 GHz | 45 W | BGA1440 |
| R32T | I3-7100H | B-0 | 3 MB | 2 | 2 | 0.35 GHz | 0.95 GHz | 2400 | 2133 | 3 GHz | 3 GHz | 35 W | BGA1440 |

§



Summary Tables of Changes

The following table indicates the Specification Changes, Errata, Specification Clarifications or Documentation Changes, which apply to the listed processor stepping. Intel intends to fix some of the errata in a future stepping of the component, and to account for the other outstanding issues through documentation or Specification Changes as noted. This table uses the following notations:

Codes Used in Summary Table

Stepping

- X: Erratum, Specification Change or Clarification that applies to this stepping.
- (No mark) or (Blank Box): This erratum is fixed in listed stepping or specification change does not apply to listed stepping.

Status

- Doc: Document change or update that will be implemented.
- Plan Fix: This erratum may be fixed in a future stepping of the product.
- Fixed: This erratum has been previously fixed.
- No Fix: There are no plans to fix this erratum.



Errata Summary Table

Table 13. Errata Summary Table

| Erratum ID | Processor Line / Stepping | | | | | | | Status | Title |
|------------|---------------------------|--------------|-------|---------------|-----------|-------|-------|--------|---|
| | KBL-Y | | KBL-U | | | KBL-H | KBL-S | | |
| | H-0 | H-0 iHDCP2.2 | H-0 | H-0 iHDCP 2.2 | J-1 (23e) | B-0 | B-0 | | |
| KBL001 | X | X | X | X | X | X | X | No Fix | Reported Memory Type May Not Be Used to Access the VMCS and Referenced Data Structures |
| KBL002 | X | X | X | X | X | X | X | No Fix | Instruction Fetch May Cause Machine Check if Page Size and Memory Type Was Changed Without Invalidation |
| KBL003 | X | X | X | X | X | X | X | No Fix | Execution of VAESIMC or VAESKEYGENASSIST With An Illegal Value for VEX.vvvv May Produce a #NM Exception |
| KBL004 | X | X | X | X | X | X | X | No Fix | The Corrected Error Count Overflow Bit in IA32_MCO_STATUS is Not Updated When The UC Bit is Set |
| KBL005 | X | X | X | X | X | X | X | No Fix | VM Exit May Set IA32_EFER.NXE When IA32_MISC_ENABLE Bit 34 is Set to 1 |
| KBL006 | X | X | X | X | X | X | X | No Fix | SMRAM State-Save Area Above the 4GB Boundary May Cause Unpredictable System Behavior |
| KBL007 | X | X | X | X | X | X | X | No Fix | x87 FPU Exception (#MF) May be Signaled Earlier Than Expected |
| KBL008 | X | X | X | X | X | X | X | No Fix | Incorrect FROM_IP Value For an RTM Abort in BTM or BTS May be Observed |
| KBL009 | X | X | X | X | X | X | X | No Fix | DR6 Register May Contain an Incorrect Value When a MOV to SS or POP SS Instruction is Followed by an XBEGIN Instruction |
| KBL010 | X | X | X | X | X | X | X | No Fix | Opcode Bytes F3 OF BC May Execute As TZCNT Even When TZCNT Not Enumerated by CPUID |
| KBL011 | X | X | X | X | X | X | X | No Fix | #GP on Segment Selector Descriptor that Straddles Canonical Boundary May Not Provide Correct Exception Error Code |
| KBL012 | X | X | X | X | X | X | X | No Fix | The SMSW Instruction May Execute Within an Enclave |



| Erratum ID | Processor Line / Stepping | | | | | | | Status | Title |
|------------|---------------------------|--------------|-------|---------------|-----------|-------|-------|--------|---|
| | KBL-Y | | KBL-U | | | KBL-H | KBL-S | | |
| | H-0 | H-0 iHDCP2.2 | H-0 | H-0 iHDCP 2.2 | J-1 (23e) | B-0 | B-0 | | |
| KBL013 | X | X | X | X | X | X | X | No Fix | WRMSR to IA32_BIOS_UPDT_TRIG Concurrent With an SMX SENTER/SEXIT May Result in a System Hang |
| KBL014 | X | X | X | X | X | X | X | No Fix | Intel® PT TIP.PGD May Not Have Target IP Payload |
| KBL015 | X | X | X | X | X | X | X | No Fix | Operand-Size Override Prefix Causes 64-bit Operand Form of MOVBE Instruction to Cause a #UD |
| KBL016 | X | X | X | X | X | X | X | No Fix | Execution of FXSAVE or FXRSTOR With the VEX Prefix May Produce a #NM Exception |
| KBL017 | X | X | X | X | X | X | X | No Fix | WRMSR May Not Clear The Sticky Count Overflow Bit in The IA32_MCI_STATUS MSRs' Corrected Error Count Field |
| KBL018 | X | X | X | X | X | X | X | No Fix | PEBS Eventing IP Field May be Incorrect After Not-Taken Branch |
| KBL019 | X | X | X | X | X | X | X | No Fix | Debug Exceptions May Be Lost or Misreported Following WRMSR to IA32_BIOS_UPDT_TRIG |
| KBL020 | X | X | X | X | X | X | X | No Fix | Complex Interactions With Internal Graphics May Impact Processor Responsiveness |
| KBL021 | X | X | X | X | X | X | X | No Fix | Intel® Processor Trace PSB+ Packets May Contain Unexpected Packets |
| KBL022 | X | X | X | X | X | X | X | No Fix | Placing an Intel® PT ToPA in Non-WB Memory or Writing It Within a Transactional Region May Lead to System Instability |
| KBL023 | X | X | X | X | X | X | X | No Fix | VM Entry That Clears TraceEn May Generate a FUP |
| KBL024 | X | X | X | X | X | X | X | No Fix | Performance Monitor Event For Outstanding Offcore Requests And Snoop Requests May be Incorrect |
| KBL025 | X | X | X | X | X | X | X | No Fix | ENCLU[EGETKEY] Ignores KEYREQUEST.MISCMASK |
| KBL026 | X | X | X | X | X | X | X | No Fix | POPCNT Instruction May Take Longer to Execute Than Expected |
| KBL027 | X | X | X | X | X | X | X | No Fix | ENCLU[EREPORT] May Cause a #GP When TARGETINFO.MISCSELECT is Non-Zero |



| Erratum ID | Processor Line / Stepping | | | | | | | Status | Title |
|------------|---------------------------|--------------|-------|---------------|-----------|-------|-------|--------|---|
| | KBL-Y | | KBL-U | | | KBL-H | KBL-S | | |
| | H-0 | H-0 iHDCP2.2 | H-0 | H-0 iHDCP 2.2 | J-1 (23e) | B-0 | B-0 | | |
| KBL028 | X | X | X | X | X | X | X | No Fix | A VMX Transition Attempting to Load a Non-Existent MSR May Result in a Shutdown |
| KBL029 | X | X | X | X | X | X | X | No Fix | Transitions Out of 64-bit Mode May Lead to an Incorrect FDP And FIP |
| KBL030 | X | X | X | X | X | X | X | No Fix | Intel® PT FUP May be Dropped After OVF |
| KBL031 | X | X | X | X | X | X | X | No Fix | ENCLS[ECREATE] Causes #GP if Enclave Base Address is Not Canonical |
| KBL032 | X | X | X | X | X | X | X | No Fix | Processor Graphics IOMMU Unit May Report Spurious Faults |
| KBL033 | X | X | X | X | X | X | X | No Fix | Processor DDR VREF Signals May Briefly Exceed JEDEC Spec When Entering S3 State |
| KBL034 | X | X | X | X | X | X | X | No Fix | DR6.B0-B3 May Not Report All Breakpoints Matched When a MOV/POP SS is Followed by a Store or an MMX Instruction |
| KBL035 | X | X | X | X | X | X | X | No Fix | ENCLS[EINIT] Instruction May Unexpectedly #GP |
| KBL036 | X | X | X | X | X | X | X | No Fix | Intel® PT OVF Packet May be Lost if Immediately Preceding a TraceStop |
| KBL037 | X | X | X | X | X | X | X | No Fix | WRMSR to IA32_BIOS_UPDT_TRIG May be Counted as Multiple Instructions |
| KBL038 | X | X | X | X | X | X | X | No Fix | Branch Instructions May Initialize MPX Bound Registers Incorrectly |
| KBL039 | X | X | X | X | X | X | X | No Fix | Writing a Non-Canonical Value to an LBR MSR Does Not Signal a #GP When Intel® PT is Enabled |
| KBL040 | X | X | X | X | X | X | X | No Fix | Processor May Run Intel® AVX Code Much Slower Than Expected |
| KBL041 | X | X | X | X | X | X | X | No Fix | Intel® PT Buffer Overflow May Result in Incorrect Packets |
| KBL042 | X | X | X | X | X | X | X | No Fix | Last Level Cache Performance Monitoring Events May Be Inaccurate |
| KBL043 | X | X | X | X | X | X | X | No Fix | #GP Occurs Rather Than #DB on Code Page Split Inside an Intel® SGX Enclave |



| Erratum ID | Processor Line / Stepping | | | | | | | Status | Title |
|------------|---------------------------|--------------|-------|---------------|-----------|-------|-------|--------|--|
| | KBL-Y | | KBL-U | | | KBL-H | KBL-S | | |
| | H-0 | H-0 iHDCP2.2 | H-0 | H-0 iHDCP 2.2 | J-1 (23e) | B-0 | B-0 | | |
| KBL044 | X | X | X | X | X | X | X | No Fix | Execution of VAESENCLAST Instruction May Produce a #NM Exception Instead of a #UD Exception |
| KBL045 | X | X | X | X | X | X | X | No Fix | Intel® SGX Enclave Accesses to the APIC-Access Page May Cause APIC-Access VM Exits |
| KBL046 | X | X | X | X | X | X | X | No Fix | CR3 Filtering Does Not Compare Bits [11:5] of CR3 and IA32_RTIT_CR3_MATCH in PAE Paging Mode |
| KBL047 | X | X | X | X | X | X | X | No Fix | x87 FDP Value May be Saved Incorrectly |
| KBL048 | X | X | X | X | X | X | X | No Fix | PECI Frequency Limited to 1 MHz |
| KBL049 | X | X | X | X | X | X | X | No Fix | Processor Graphics IOMMU Unit May Not Mask DMA Remapping Faults |
| KBL050 | X | X | X | X | X | X | X | No Fix | Intel® PT CYCThresh Value of 13 is Not Supported |
| KBL051 | X | X | X | X | X | X | X | No Fix | Enabling VMX-Preemption Timer Blocks HDC Operation |
| KBL052 | X | X | X | X | X | X | X | No Fix | Integrated Audio Codec May Not be Detected |
| KBL053 | X | X | X | X | X | X | X | No Fix | Display Flickering May be Observed with Specific eDP Panels |
| KBL054 | X | X | X | X | X | X | X | No Fix | Incorrect Branch Predicted Bit in BTS/BTM Branch Records |
| KBL055 | X | X | X | X | X | X | X | No Fix | MACHINE_CLEARS.MEMORY ORDERING Performance Monitoring Event May Undercount |
| KBL056 | X | X | X | X | X | X | X | No Fix | Some Counters May Not Freeze On Performance Monitoring Interrupts |
| KBL057 | X | X | X | X | X | X | X | No Fix | Instructions And Branches Retired Performance Monitoring Events May Overcount |
| KBL058 | X | X | X | X | X | X | X | No Fix | Some OFFCORE_RESPONSE Performance Monitoring Events May Overcount |
| KBL059 | X | X | X | X | X | X | X | No Fix | #GP After RSM May Push Incorrect RFLAGS Value When Intel® PT is Enabled |



Summary Tables of Changes

| Erratum ID | Processor Line / Stepping | | | | | | | Status | Title |
|---------------------|---------------------------|--------------|-------|---------------|-----------|-------|-------|--------|--|
| | KBL-Y | | KBL-U | | | KBL-H | KBL-S | | |
| | H-0 | H-0 iHDCP2.2 | H-0 | H-0 iHDCP 2.2 | J-1 (23e) | B-0 | B-0 | | |
| KBL060 | X | X | X | X | X | X | X | No Fix | Access to SGX EPC Page in BLOCKED State is Not KBL062Reported as an SGX-Induced Page Fault |
| KBL061 | X | X | X | X | X | X | X | No Fix | MTF VM Exit on XBEGIN Instruction May Save State Incorrectly |
| KBL062 ¹ | X | | X | | | | | Fixed | Intel® Turbo Boost Technology May be Incorrectly Reported as Supported on Intel® Core™ i3 U/H/S, Intel® Mobile Pentium®, Intel® Mobile Celeron®, Select Intel® Pentium® and Intel® Celeron® Processors |
| KBL063 | X | X | X | X | X | X | X | No Fix | Performance Monitoring Counters May Undercount When Using CPL Filtering |
| KBL064 | X | | X | | | | | No Fix | Executing a 256 Bit AVX Instruction May Cause Unpredictable Behavior |
| KBL065 | X | | X | | | | | No Fix | System May Hang During Display Power Cycles |
| KBL066 | X | X | X | X | X | X | X | No Fix | Certain Non-Canonical IA32_BNDCFGS Values Will Not Cause VM-Entry Failures |
| KBL067 | X | X | X | X | X | X | X | No Fix | PEBS EventingIP Field May Be Incorrect Under Certain Conditions |
| KBL068 | X | X | X | X | X | X | X | No Fix | HWP's Guaranteed_Performance Updated Only on Configurable TDP Changes |
| KBL069 | X | X | X | X | X | X | X | No Fix | RF May be Incorrectly Set in The EFLAGS That is Saved on a Fault in PEBS or BTS |
| KBL070 | X | X | X | X | X | X | X | No Fix | Intel® PT ToPA PMI Does Not Freeze Performance Monitoring Counters |
| KBL071 | X | X | X | X | X | X | X | No Fix | HWP's Maximum_Performance Value is Reset to 0xFF |
| KBL072 | X | X | X | X | X | X | X | No Fix | HWP's Guaranteed_Performance and Relevant Status/Interrupt May be Updated More Than Once Per Second |
| KBL073 | X | X | X | X | X | X | X | No Fix | Some Memory Performance Monitoring Events May Produce Incorrect Results When Filtering on Either OS or USR Modes |
| KBL074 | X | X | X | X | X | X | X | No Fix | HWP May Generate Thermal Interrupt While Not Enabled |



| Erratum ID | Processor Line / Stepping | | | | | | | Status | Title |
|------------|---------------------------|--------------|-------|---------------|-----------|-------|-------|--------|--|
| | KBL-Y | | KBL-U | | | KBL-H | KBL-S | | |
| | H-0 | H-0 iHDCP2.2 | H-0 | H-0 iHDCP 2.2 | J-1 (23e) | B-0 | B-0 | | |
| KBL075 | X | X | X | X | X | X | X | No Fix | Camera Device Does Not Issue an MSI When INTx is Enabled |
| KBL076 | X | | X | | | | | No Fix | An x87 Store Instruction Which Pends #PE May Lead to Unexpected Behavior When EPT A/D is Enabled. |
| KBL077 | X | | X | | | | | No Fix | Use of VMASKMOV to Store When Using EPT May Fail |
| KBL078 | X | X | X | X | | X | | No Fix | PECI May Not be Functional After Package C10 Resume |
| KBL079 | | | | | | X | X | No Fix | Attempts to Retrain a PCIe* Link May be Ignored |
| KBL080 | | | | | | X | X | Fixed | PCIe* Expansion ROM Base Address Register May be Incorrect |
| KBL081 | | | | | | X | X | No Fix | PCIe* Port Does Not Support DLL Link Activity Reporting |
| KBL082 | X | X | X | X | X | X | X | No Fix | BNDLDX And BNDSTX May Not Signal #GP on Non-Canonical Bound Directory Access |
| KBL083 | X | X | X | X | X | X | X | No Fix | RING_PERF_LIMIT_REASONS May be Incorrect |
| KBL084 | | | | | | X | X | No Fix | Processor May Exceed VCCCore ICCMAX During Multi-core Turbo |
| KBL085 | X | X | X | X | X | X | X | No Fix | Performance Monitoring Load Latency Events May Be Inaccurate For Gather Instructions |
| KBL086 | | | | | X | | | No Fix | EDRAM Corrected Error Events May Not be Properly Logged After a Warm Reset |
| KBL087 | X | X | X | X | X | | | No Fix | Unpredictable System Behavior May Occur When System Agent Enhanced Intel® Speedstep® is Enabled |
| KBL088 | X | X | X | X | X | X | X | No Fix | Processor May Hang Under Complex Scenarios |
| KBL089 | X | X | X | X | X | X | X | No Fix | Some Bits in MSR_MISC_PWR_MGMT May be Updated on Writing Illegal Values to This MSR |
| KBL090 | X | X | X | X | X | X | X | No Fix | Violations of Intel® Software Guard Extensions (Intel® SGX) Access-Control Requirements Produce #GP Instead of #PF |



| Erratum ID | Processor Line / Stepping | | | | | | | Status | Title |
|------------|---------------------------|--------------|-------|---------------|-----------|-------|-------|--------|--|
| | KBL-Y | | KBL-U | | | KBL-H | KBL-S | | |
| | H-0 | H-0 iHDCP2.2 | H-0 | H-0 iHDCP 2.2 | J-1 (23e) | B-0 | B-0 | | |
| KBL091 | X | X | X | X | X | X | X | No Fix | IA32_RTIT_CR3_MATCH MSR Bits[11:5] Are Treated As Reserved |
| KBL092 | X | X | X | X | X | X | X | X | APIC Timer Interrupt May Not be Generated at The Correct Time In TSC-Deadline Mode |
| KBL093 | X | X | X | X | X | X | X | X | The Intel PT CR3 Filter is Not Re-evaluated on VM Entry |
| KBL094 | X | X | X | X | X | X | X | X | Display Slowness May be Observed Under Certain Display Commands Scenario |

Notes:

1. Affects 7th Generation Intel® Core™ i3 U, Intel® Pentium®, Intel® Celeron® Processors.
2. Processor line and Stepping information:
 - Y-Processor Line stepping H-0:
 - Without iHDCP2.2 (Mobile)
 - With iHDCP2.2 (Mobile)
 - U-Processor Line stepping: H-0
 - Without iHDCP2.2 (Mobile)
 - With iHDCP2.2 (Mobile)





Errata

| | |
|--------------------|--|
| KBL001 | Reported Memory Type May Not Be Used to Access the VMCS and Referenced Data Structures |
| Problem | Bits 53:50 of the IA32_VMX_BASIC MSR report the memory type that the processor uses to access the VMCS and data structures referenced by pointers in the VMCS. Due to this erratum, a VMX access to the VMCS or referenced data structures will instead use the memory type that the MTRRs (memory-type range registers) specify for the physical address of the access. |
| Implication | Bits 53:50 of the IA32_VMX_BASIC MSR report that the WB (write-back) memory type will be used but the processor may use a different memory type. |
| Workaround | Software should ensure that the VMCS and referenced data structures are located at physical addresses that are mapped to WB memory type by the MTRRs. |
| Status | For the steppings affected, see the Summary Table of Changes. |

| | |
|--------------------|---|
| KBL002 | Instruction Fetch May Cause Machine Check if Page Size and Memory Type Was Changed Without Invalidation |
| Problem | This erratum may cause a machine-check error (IA32_MCI_STATUS.MCACOD=0150H) on the fetch of an instruction that crosses a 4-KByte address boundary. It applies only if (1) the 4-KByte linear region on which the instruction begins is originally translated using a 4-KByte page with the WB memory type; (2) the paging structures are later modified so that linear region is translated using a large page (2-MByte, 4-MByte, or 1-GByte) with the UC memory type; and (3) the instruction fetch occurs after the paging-structure modification but before software invalidates any TLB entries for the linear region. |
| Implication | Due to this erratum an unexpected machine check with error code 0150H may occur, possibly resulting in a shutdown. Intel has not observed this erratum with any commercially available software. |
| Workaround | Software should not write to a paging-structure entry in a way that would change, for any linear address, both the page size and the memory type. It can instead use the following algorithm: first clear the P flag in the relevant paging-structure entry (e.g., PDE); then invalidate any translations for the affected linear addresses; and then modify the relevant paging-structure entry to set the P flag and establish the new page size and memory type. |
| Status | For the steppings affected, see the Summary Table of Changes. |

| | |
|--------------------|---|
| KBL003 | Execution of VAESIMC or VAESKEYGENASSIST With An Illegal Value for VEX.vvvv May Produce a #NM Exception |
| Problem | The VAESIMC and VAESKEYGENASSIST instructions should produce a #UD (Invalid-Opcode) exception if the value of the vvvv field in the VEX prefix is not 1111b. Due to this erratum, if CR0.TS is "1", the processor may instead produce a #NM (Device-Not-Available) exception. |
| Implication | Due to this erratum, some undefined instruction encodings may produce a #NM instead of a #UD exception. |
| Workaround | Software should always set the vvvv field of the VEX prefix to 1111b for instances of the VAESIMC and VAESKEYGENASSIST instructions. |



| | |
|---------------|---|
| Status | For the steppings affected, see the Summary Table of Changes. |
|---------------|---|

| | |
|--------------------|--|
| KBL004 | The Corrected Error Count Overflow Bit in IA32_MCO_STATUS is Not Updated When The UC Bit is Set |
| Problem | After a UC (uncorrected) error is logged in the IA32_MCO_STATUS MSR (401H), corrected errors will continue to be counted in the lower 14 bits (bits 51:38) of the Corrected Error Count. Due to this erratum, the sticky count overflow bit (bit 52) of the Corrected Error Count will not get updated when the UC bit (bit 61) is set to 1. |
| Implication | The Corrected Error Count Overflow indication will be lost if the overflow occurs after an uncorrectable error has been logged. |
| Workaround | None identified |
| Status | For the steppings affected, see the Summary Table of Changes. |

| | |
|--------------------|---|
| KBL005 | VM Exit May Set IA32_EFER.NXE When IA32_MISC_ENABLE Bit 34 is Set to 1 |
| Problem | When “XD Bit Disable” in the IA32_MISC_ENABLE MSR (1A0H) bit 34 is set to 1, it should not be possible to enable the “execute disable” feature by setting IA32_EFER.NXE. Due to this erratum, a VM exit that occurs with the 1-setting of the “load IA32_EFER” VM-exit control may set IA32_EFER.NXE even if IA32_MISC_ENABLE bit 34 is set to 1. This erratum can occur only if IA32_MISC_ENABLE bit 34 was set by guest software in VMX non-root operation. |
| Implication | Software in VMX root operation may execute with the “execute disable” feature enabled despite the fact that the feature should be disabled by the IA32_MISC_ENABLE MSR. Intel has not observed this erratum with any commercially available software. |
| Workaround | A virtual-machine monitor should not allow guest software to write to the IA32_MISC_ENABLE MSR |
| Status | For the steppings affected, see the Summary Table of Changes. |

| | |
|--------------------|--|
| KBL006 | SMRAM State-Save Area Above the 4GB Boundary May Cause Unpredictable System Behavior |
| Problem | If BIOS uses the RSM instruction to load the SMBASE register with a value that would cause any part of the SMRAM state-save area to have an address above 4-GBytes, subsequent transitions into and out of SMM (system-management mode) might save and restore processor state from incorrect addresses. |
| Implication | This erratum may cause unpredictable system behavior. Intel has not observed this erratum with any commercially available system. |
| Workaround | Ensure that the SMRAM state-save area is located entirely below the 4GB address boundary. |
| Status | For the steppings affected, see the Summary Table of Changes. |



| | |
|--------------------|--|
| KBL007 | x87 FPU Exception (#MF) May be Signaled Earlier Than Expected |
| Problem | x87 instructions that trigger #MF normally service interrupts before the #MF. Due to this erratum, if an instruction that triggers #MF is executing when an Enhanced Intel SpeedStep® Technology transitions, an Intel® Turbo Boost Technology transitions, or a Thermal Monitor events occurs, the #MF may be taken before pending interrupts are serviced. |
| Implication | Software may observe #MF being signaled before pending interrupts are serviced. |
| Workaround | None identified. |
| Status | For the steppings affected, see the Summary Table of Changes. |

| | |
|--------------------|---|
| KBL008 | Incorrect FROM_IP Value For an RTM Abort in BTM or BTS May be Observed |
| Problem | During RTM (Restricted Transactional Memory) operation when branch tracing is enabled using BTM (Branch Trace Message) or BTS (Branch Trace Store), the incorrect EIP value (From_IP pointer) may be observed for an RTM abort. |
| Implication | Due to this erratum, the From_IP pointer may be the same as that of the immediately preceding taken branch. |
| Workaround | None identified. |
| Status | For the steppings affected, see the Summary Table of Changes. |

| | |
|--------------------|--|
| KBL009 | DR6 Register May Contain an Incorrect Value When a MOV to SS or POP SS Instruction is Followed by an XBEGIN Instruction |
| Problem | If XBEGIN is executed immediately after an execution of MOV to SS or POP SS, a transactional abort occurs and the logical processor restarts execution from the fallback instruction address. If execution of the instruction at that address causes a debug exception, bits [3:0] of the DR6 register may contain an incorrect value. |
| Implication | When the instruction at the fallback instruction address causes a debug exception, DR6 may report a breakpoint that was not triggered by that instruction, or it may fail to report a breakpoint that was triggered by the instruction. |
| Workaround | Avoid following a MOV SS or POP SS instruction immediately with an XBEGIN instruction. |
| Status | For the steppings affected, see the Summary Table of Changes. |

| | |
|--------------------|--|
| KBL010 | Opcode Bytes F3 0F BC May Execute As TZCNT Even When TZCNT Not Enumerated by CPUID |
| Problem | If CPUID.(EAX=07H, ECX=0):EBX.BMI1 (bit 3) is 1 then opcode bytes F3 0F BC should be interpreted as TZCNT otherwise they will be interpreted as REP BSF. Due to this erratum, opcode bytes F3 0F BC may execute as TZCNT even if CPUID.(EAX=07H, ECX=0):EBX.BMI1 (bit 3) is 0. |
| Implication | Software that expects REP prefix before a BSF instruction to be ignored may not operate correctly since there are cases in which BSF and TZCNT differ with regard to the flags that are set and how the destination operand is established. |
| Workaround | Software should use the opcode bytes F3 0F BC only if CPUID.(EAX=07H, ECX=0):EBX.BMI1 (bit 3) is 1 and only if the functionality of TZCNT (and not BSF) is desired. |



| | |
|---------------|---|
| Status | For the steppings affected, see the Summary Table of Changes. |
|---------------|---|

| | |
|--------------------|--|
| KBL011 | #GP on Segment Selector Descriptor that Straddles Canonical Boundary May Not Provide Correct Exception Error Code |
| Problem | During a #GP (General Protection Exception), the processor pushes an error code on to the exception handler's stack. If the segment selector descriptor straddles the canonical boundary, the error code pushed onto the stack may be incorrect. |
| Implication | An incorrect error code may be pushed onto the stack. Intel has not observed this erratum with any commercially available software. |
| Workaround | None identified. |
| Status | For the steppings affected, see the Summary Table of Changes. |

| | |
|--------------------|---|
| KBL012 | The SMSW Instruction May Execute Within an Enclave |
| Problem | The SMSW instruction is illegal within an SGX (Software Guard Extensions) enclave, and an attempt to execute it within an enclave should result in a #UD (invalid-opcode exception). Due to this erratum, the instruction executes normally within an enclave and does not cause a #UD. |
| Implication | The SMSW instruction provides access to CR0 bits 15:0 and will provide that information inside an enclave. These bits include NE, ET, TS, EM, MP and PE. |
| Workaround | None identified. If SMSW execution inside an enclave is unacceptable, system software should not enable SGX. |
| Status | For the steppings affected, see the Summary Table of Changes. |

| | |
|--------------------|--|
| KBL013 | WRMSR to IA32_BIOS_UPDT_TRIG Concurrent With an SMX SENTER/SEXIT May Result in a System Hang |
| Problem | Performing WRMSR to IA32_BIOS_UPDT_TRIG (MSR 79H) on a logical processor while another logical processor is executing an SMX (Safer Mode Extensions) SENTER/SEXIT operation (GETSEC[SENTER] or GETSEC[SEXIT] instruction) may cause the processor to hang. |
| Implication | When this erratum occurs, the system will hang. Intel has not observed this erratum with any commercially available system. |
| Workaround | None identified. |
| Status | For the steppings affected, see the Summary Table of Changes. |

| | |
|--------------------|--|
| KBL014 | Intel® PT TIP.PGD May Not Have Target IP Payload |
| Problem | When Intel PT (Intel Processor Trace) is enabled and a direct unconditional branch clears IA32_RTIT_STATUS.FilterEn (MSR 571H, bit 0), due to this erratum, the resulting TIP.PGD (Target IP Packet, Packet Generation Disable) may not have an IP payload with the target IP. |
| Implication | It may not be possible to tell which instruction in the flow caused the TIP.PGD using only the information in trace packets when this erratum occurs. |
| Workaround | The Intel PT trace decoder can compare direct unconditional branch targets in the source with the FilterEn address range(s) to determine which branch cleared FilterEn. |



| | |
|---------------|---|
| Status | For the steppings affected, see the Summary Table of Changes. |
|---------------|---|

| | |
|--------------------|---|
| KBL015 | Operand-Size Override Prefix Causes 64-bit Operand Form of MOVBE Instruction to Cause a #UD |
| Problem | Execution of a 64 bit operand MOVBE instruction with an operand-size override instruction prefix (66H) may incorrectly cause an invalid-opcode exception (#UD). |
| Implication | A MOVBE instruction with both REX.W=1 and a 66H prefix will unexpectedly cause an #UD (invalid-opcode exception). Intel has not observed this erratum with any commercially available software. |
| Workaround | Do not use a 66H instruction prefix with a 64-bit operand MOVBE instruction. |
| Status | For the steppings affected, see the Summary Table of Changes. |

| | |
|--------------------|--|
| KBL016 | Execution of FXSAVE or FXRSTOR With the VEX Prefix May Produce a #NM Exception |
| Problem | Attempt to use FXSAVE or FXRSTOR with a VEX prefix should produce a #UD (Invalid-Opcode) exception. If either the TS or EM flag bits in CR0 are set, a #NM (device-not-available) exception will be raised instead of #UD exception. |
| Implication | Due to this erratum a #NM exception may be signaled instead of a #UD exception on an FXSAVE or an FXRSTOR with a VEX prefix. |
| Workaround | Software should not use FXSAVE or FXRSTOR with the VEX prefix. |
| Status | For the steppings affected, see the Summary Table of Changes. |

| | |
|--------------------|--|
| KBL017 | WRMSR May Not Clear The Sticky Count Overflow Bit in The IA32_MCI_STATUS MSRs' Corrected Error Count Field |
| Problem | The sticky count overflow bit is the most significant bit (bit 52) of the Corrected Error Count Field (bits[52:38]) in IA32_MCI_STATUS MSRs. Once set, the sticky count overflow bit may not be cleared by a WRMSR instruction. When this occurs, that bit can only be cleared by power-on reset. |
| Implication | Software that uses the Corrected Error Count field and expects to be able to clear the sticky count overflow bit may misinterpret the number of corrected errors when the sticky count overflow bit is set. This erratum does not affect threshold-based CMCI (Corrected Machine Check Error Interrupt) signaling. |
| Workaround | None identified. |
| Status | For the steppings affected, see the Summary Table of Changes. |

| | |
|--------------------|--|
| KBL018 | PEBS Eventing IP Field May be Incorrect After Not-Taken Branch |
| Problem | When a PEBS (Precise-Event-Based-Sampling) record is logged immediately after a not-taken conditional branch (Jcc instruction), the Eventing IP field should contain the address of the first byte of the Jcc instruction. Due to this erratum, it may instead contain the address of the instruction preceding the Jcc instruction. |
| Implication | Performance monitoring software using PEBS may incorrectly attribute PEBS events that occur on a Jcc to the preceding instruction. |
| Workaround | None identified. |



| | |
|--------------------|--|
| Status | For the steppings affected, see the Summary Table of Changes. |
| KBL019 | Debug Exceptions May Be Lost or Misreported Following WRMSR to IA32_BIOS_UPDT_TRIG |
| Problem | If the WRMSR instruction writes to the IA32_BIOS_UPDT_TRIG MSR (79H) immediately after an execution of MOV SS or POP SS that generated a debug exception, the processor may fail to deliver the debug exception or, if it does, the DR6 register contents may not correctly reflect the causes of the debug exception. |
| Implication | Debugging software may fail to operate properly if a debug exception is lost or does not report complete information. |
| Workaround | Software should avoid using WRMSR instruction immediately after executing MOV SS or POP SS |
| Status | For the steppings affected, see the Summary Table of Changes. |
| KBL020 | Complex Interactions With Internal Graphics May Impact Processor Responsiveness |
| Problem | Under complex conditions associated with the use of internal graphics, the processor may exceed the MAX_LAT CSR values (PCI configuration space, offset 03FH, bits[7:0]). |
| Implication | When this erratum occurs, the processor responsiveness is affected. Intel has not observed this erratum with any commercially available software. |
| Workaround | None identified. |
| Status | For the steppings affected, see the Summary Table of Changes. |
| KBL021 | Intel® Processor Trace PSB+ Packets May Contain Unexpected Packets |
| Problem | Some Intel Processor Trace packets should be issued only between TIP.PGE (Target IP Packet.Packet Generation Enable) and TIP.PGD (Target IP Packet.Packet Generation Disable) packets. Due to this erratum, when a TIP.PGE packet is generated it may be preceded by a PSB+ (Packet Stream Boundary) that incorrectly includes FUP (Flow Update Packet) and MODE.Exec packets. |
| Implication | Due to this erratum, FUP and MODE.Exec may be generated unexpectedly. |
| Workaround | Decoders should ignore FUP and MODE.Exec packets that are not between TIP.PGE and TIP.PGD packets. |
| Status | For the steppings affected, see the Summary Table of Changes. |
| KBL022 | Placing an Intel® PT ToPA in Non-WB Memory or Writing It Within a Transactional Region May Lead to System Instability |
| Problem | If an Intel PT (Intel® Processor Trace) ToPA (Table of Physical Addresses) is not placed in WB (writeback) memory or is written by software executing within an Intel® TSX (Intel® Transactional Synchronization Extension) transactional region, the system may become unstable. |
| Implication | Unusual treatment of the ToPA may lead to system instability. |
| Workaround | None identified. Intel PT ToPA should reside in WB memory and should not be written within a Transactional Region. |



| | |
|---------------|---|
| Status | For the steppings affected, see the Summary Table of Changes. |
|---------------|---|

| | |
|--------------------|--|
| KBL023 | VM Entry That Clears TraceEn May Generate a FUP |
| Problem | If VM entry clears Intel® PT (Intel Processor Trace) IA32_RTIT_CTL.TraceEn (MSR 570H, bit 0) while PacketEn is 1 then a FUP (Flow Update Packet) will precede the TIP.PGD (Target IP Packet, Packet Generation Disable). VM entry can clear TraceEn if the VM-entry MSR-load area includes an entry for the IA32_RTIT_CTL MSR. |
| Implication | When this erratum occurs, an unexpected FUP may be generated that creates the appearance of an asynchronous event taking place immediately before or during the VM entry. |
| Workaround | The Intel PT trace decoder may opt to ignore any FUP whose IP matches that of a VM entry instruction. |
| Status | For the steppings affected, see the Summary Table of Changes. |

| | |
|--------------------|---|
| KBL024 | Performance Monitor Event For Outstanding Offcore Requests And Snoop Requests May be Incorrect |
| Problem | The performance monitor event OFFCORE_REQUESTS_OUTSTANDING (Event 60H, any Umask Value) should count the number of offcore outstanding transactions each cycle. Due to this erratum, the counts may be higher or lower than expected. |
| Implication | The performance monitor event OFFCORE_REQUESTS_OUTSTANDING may reflect an incorrect count. |
| Workaround | None identified. |
| Status | For the steppings affected, see the Summary Table of Changes. |

| | |
|--------------------|---|
| KBL025 | ENCLU[EGETKEY] Ignores KEYREQUEST.MISCMASK |
| Problem | The Intel® SGX (Software Guard Extensions) ENCLU[EGETKEY] instruction ignores the MISCMASK field in KEYREQUEST structure when computing a provisioning key, a provisioning seal key, or a seal key. |
| Implication | ENCLU[EGETKEY] will return the same key in response to two requests that differ only in the value of KEYREQUEST.MISCMASK. Intel has not observed this erratum with any commercially available software. |
| Workaround | When executing the ENCLU[EGETKEY] instruction, software should ensure the bits set in KEYREQUEST.MISCMASK are a subset of the bits set in the current SECS's MISCSELECT field. |
| Status | For the steppings affected, see the Summary Table of Changes. |

| | |
|--------------------|--|
| KBL026 | POPCNT Instruction May Take Longer to Execute Than Expected |
| Problem | POPCNT instruction execution with a 32 or 64 bit operand may be delayed until previous non-dependent instructions have executed. |
| Implication | Software using the POPCNT instruction may experience lower performance than expected. |
| Workaround | None identified |
| Status | For the steppings affected, see the Summary Table of Changes. |



| | |
|--------------------|--|
| KBL027 | ENCLU[EREPORT] May Cause a #GP When TARGETINFO.MISCSELECT is Non-Zero |
| Problem | The Intel® SGX (Software Guard extensions) ENCLU[EREPORT] instruction may cause a #GP (general protection fault) if any bit is set in TARGETINFO structure's MISCSELECT field. |
| Implication | This erratum may cause unexpected general-protection exceptions inside enclaves. |
| Workaround | When executing the ENCLU[EREPORT] instruction, software should ensure the bits set in TARGETINFO.MISCSELECT are a subset of the bits set in the current SECS's MISCSELECT field. |
| Status | For the steppings affected, see the Summary Table of Changes. |

| | |
|--------------------|---|
| KBL028 | A VMX Transition Attempting to Load a Non-Existent MSR May Result in a Shutdown |
| Problem | A VMX transition may result in a shutdown (without generating a machine-check event) if a non-existent MSR is included in the associated MSR-load area. When such a shutdown occurs, a machine check error will be logged with IA32_MCI_STATUS.MCACOD (bits [15:0]) of 406H, but the processor does not issue the special shutdown cycle. A hardware reset must be used to restart the processor. |
| Implication | Due to this erratum, the hypervisor may experience an unexpected shutdown. |
| Workaround | Software should not configure VMX transitions to load non-existent MSRs. |
| Status | For the steppings affected, see the Summary Table of Changes. |

| | |
|--------------------|---|
| KBL029 | Transitions Out of 64-bit Mode May Lead to an Incorrect FDP And FIP |
| Problem | A transition from 64-bit mode to compatibility or legacy modes may result in cause a subsequent x87 FPU state save to zeroing bits [63:32] of the FDP (x87 FPU Data Pointer Offset) and the FIP (x87 FPU Instruction Pointer Offset). |
| Implication | Leaving 64-bit mode may result in incorrect FDP and FIP values when x87 FPU state is saved. |
| Workaround | None identified. 64-bit software should save x87 FPU state before leaving 64-bit mode if it needs to access the FDP and/or FIP values. |
| Status | For the steppings affected, see the Summary Table of Changes. |

| | |
|--------------------|---|
| KBL030 | Intel® PT FUP May be Dropped After OVF |
| Problem | Some Intel PT (Intel Processor Trace) OVF (Overflow) packets may not be followed by a FUP (Flow Update Packet) or TIP.PGE (Target IP Packet, Packet Generation Enable). |
| Implication | When this erratum occurs, an unexpected packet sequence is generated. |
| Workaround | When it encounters an OVF without a following FUP or TIP.PGE, the Intel PT trace decoder should scan for the next TIP, TIP.PGE, or PSB+ to resume operation. |
| Status | For the steppings affected, see the Summary Table of Changes. |



| | |
|--------------------|---|
| KBL031 | ENCLS[ECREATE] Causes #GP if Enclave Base Address is Not Canonical |
| Problem | The ENCLS[ECREATE] instruction uses an SECS (SGX enclave control structure) referenced by the SRCPAGE pointer in the PAGEINFO structure, which is referenced by the RBX register. Due to this erratum, the instruction causes a #GP (general-protection fault) if the SECS attributes indicate that the enclave should operate in 64-bit mode and the enclave base linear address in the SECS is not canonical. |
| Implication | System software will incur a general-protection fault if it mistakenly programs the SECS with a non-canonical address. Intel has not observed this erratum with any commercially available software. |
| Workaround | System software should always specify a canonical address as the base address of the 64-bit mode enclave. |
| Status | For the steppings affected, see the Summary Table of Changes. |

| | |
|--------------------|---|
| KBL032 | Processor Graphics IOMMU Unit May Report Spurious Faults |
| Problem | The IOMMU unit for Processor Graphics pre-fetches context (or extended-context) entries to improve performance. Due to the erratum, the IOMMU unit may report spurious DMA remapping faults if prefetching encounters a context (or extended-context) entry which is not marked present. |
| Implication | Software may observe spurious DMA remapping faults when the present bit for the context (or extended-context) entry corresponding to the Processor Graphics device (Bus: 0; Device: 2; Function: 0) is cleared. These faults may be reported when the Processor Graphics device is quiescent. |
| Workaround | None identified. Instead of marking a context not present, software should mark the context (or extended-context) entry present while using the page table to indicate all the memory pages referenced by the context entry is not present. |
| Status | For the steppings affected, see the Summary Table of Changes. |

| | |
|--------------------|---|
| KBL033 | Processor DDR VREF Signals May Briefly Exceed JEDEC Spec When Entering S3 State |
| Problem | Voltage glitch of up to 200mV on the VREF signal lasting for about 1mS may be observed when entering System S3 state. This violates the JEDEC DDR specifications. |
| Implication | Intel has not observed this erratum to impact the operation of any commercially available system. |
| Workaround | None identified. |
| Status | For the steppings affected, see the Summary Table of Changes. |



| | |
|--------------------|---|
| KBL034 | DR6.B0-B3 May Not Report All Breakpoints Matched When a MOV/POP SS is Followed by a Store or an MMX Instruction |
| Problem | Normally, data breakpoints matches that occur on a MOV SS, r/m or POP SS will not cause a debug exception immediately after MOV/POP SS but will be delayed until the instruction boundary following the next instruction is reached. After the debug exception occurs, DR6.B0-B3 bits will contain information about data breakpoints matched during the MOV/POP SS as well as breakpoints detected by the following instruction. Due to this erratum, DR6.B0-B3 bits may not contain information about data breakpoints matched during the MOV/POP SS when the following instruction is either an MMX instruction that uses a memory addressing mode with an index or a store instruction. |
| Implication | When this erratum occurs, DR6 may not contain information about all breakpoints matched. This erratum will not be observed under the recommended usage of the MOV SS,r/m or POP SS instructions (i.e., following them only with an instruction that writes (E/R)SP). |
| Workaround | None identified. |
| Status | For the steppings affected, see the Summary Table of Changes. |

| | |
|--------------------|---|
| KBL035 | ENCLS[EINIT] Instruction May Unexpectedly #GP |
| Problem | When using Intel® SGX (Software Guard Extensions), the ENCLS[EINIT] instruction will incorrectly cause a #GP (general protection fault) if the MISCSELECT field of the SIGSTRUCT structure is not zero. |
| Implication | This erratum may cause an unexpected #GP, but only if software has set bits in the MISCSELECT field in SIGSTRUCT structure that do not correspond to extended features that can be written to the MISC region of the SSA (State Save Area). Intel has not observed this erratum with any commercially available software. |
| Workaround | When executing the ENCLS[EINIT] instruction, software should only set bits in the MISCSELECT field in the SIGSTRUCT structure that are enumerated as 1 by CPUID.(EAX=12H,ECX=0):EBX (the bit vector of extended features that can be written to the MISC region of the SSA). |
| Status | For the steppings affected, see the Summary Table of Changes. |

| | |
|--------------------|---|
| KBL036 | Intel® PT OVF Packet May be Lost if Immediately Preceding a TraceStop |
| Problem | If an Intel PT (Intel® Processor Trace) internal buffer overflow occurs immediately before software executes a taken branch or event that enters an Intel PT TraceStop region, the OVF (Overflow) packet may be lost. |
| Implication | The trace decoder will not see the OVF packet, nor any subsequent packets (e.g., TraceStop) that were lost due to overflow. |
| Workaround | None identified. |
| Status | For the steppings affected, see the Summary Table of Changes. |

| | |
|----------------|--|
| KBL037 | WRMSR to IA32_BIOS_UPDT_TRIG May be Counted as Multiple Instructions |
| Problem | When software loads a microcode update by writing to MSR IA32_BIOS_UPDT_TRIG (79H) on multiple logical processors in parallel, a logical processor may, due to this erratum, count the WRMSR instruction as multiple instruction-retired events. |



| | |
|--------------------|---|
| Implication | Performance monitoring with the instruction-retired event may over count by up to four extra events per instance of WRMSR which targets the IA32_BIOS_UPDT_TRIG register. |
| Workaround | None identified. |
| Status | For the steppings affected, see the Summary Table of Changes. |

| | |
|--------------------|---|
| KBL038 | Branch Instructions May Initialize MPX Bound Registers Incorrectly |
| Problem | Depending on the current Intel® MPX (Memory Protection Extensions) configuration, execution of certain branch instructions (near CALL, near RET, near JMP, and Jcc instructions) without a BND prefix (F2H) initialize the MPX bound registers. Due to this erratum, execution of such a branch instruction on a user-mode page may not use the MPX configuration register appropriate to the current privilege level (BNDCFGU for CPL 3 or BNDCFGS otherwise) for determining whether to initialize the bound registers; it may thus initialize the bound registers when it should not, or fail to initialize them when it should. |
| Implication | After a branch instruction on a user-mode page has executed, a #BR (bound-range) exception may occur when it should not have or a #BR may not occur when one should have. |
| Workaround | If supervisor software is not expected to execute instructions on user-mode pages, software can avoid this erratum by setting CR4.SMEP[bit 20] to enable supervisor-mode execution prevention (SMEP). If SMEP is not available or if supervisor software is expected to execute instructions on user-mode pages, no workaround is identified. |
| Status | For the steppings affected, see the Summary Table of Changes. |

| | |
|--------------------|---|
| KBL039 | Writing a Non-Canonical Value to an LBR MSR Does Not Signal a #GP When Intel® PT is Enabled |
| Problem | If Intel PT (Intel Processor Trace) is enabled, WRMSR will not cause a general-protection exception (#GP) on an attempt to write a non-canonical value to any of the following MSRs: <ul style="list-style-type: none"> MSR_LASTBRANCH_{0 - 31}_FROM_IP (680H – 69FH) MSR_LASTBRANCH_{0 - 31}_TO_IP (6C0H – 6DFH) MSR_LASTBRANCH_FROM_IP (1DBH) MSR_LASTBRANCH_TO_IP (1DCH) MSR_LASTINT_FROM_IP (1DDH) MSR_LASTINT_TO_IP (1DEH) Instead the same behavior will occur as if a canonical value had been written. Specifically, the WRMSR will be dropped and the MSR value will not be changed. |
| Implication | Due to this erratum, an expected #GP may not be signaled. |
| Workaround | None identified. |
| Status | For the steppings affected, see the Summary Table of Changes. |

| | |
|--------------------|---|
| KBL040 | Processor May Run Intel® AVX Code Much Slower Than Expected |
| Problem | After a C6 state exit, the execution rate of AVX instructions may be reduced. |
| Implication | Applications using AVX instructions may run slower than expected. |



| | |
|-------------------|---|
| Workaround | It is possible for the BIOS to contain a workaround |
| Status | For the steppings affected, see the Summary Table of Changes. |

| | |
|--------------------|---|
| KBL041 | Intel® PT Buffer Overflow May Result in Incorrect Packets |
| Problem | Under complex micro-architectural conditions, an Intel PT (Processor Trace) OVF (Overflow) packet may be issued after the first byte of a multi-byte CYC (Cycle Count) packet, instead of any remaining bytes of the CYC. |
| Implication | When this erratum occurs, the splicing of the CYC and OVF packets may prevent the Intel PT decoder from recognizing the overflow. The Intel PT decoder may then encounter subsequent packets that are not consistent with expected behavior. |
| Workaround | None Identified. The decoder may be able to recognize that this erratum has occurred when a two-byte CYC packet is followed by a single byte CYC, where the latter 2 bytes are 0xf302, and where the CYC packets are followed by a FUP (Flow Update Packet) and a PSB+ (Packet Stream Boundary+). It should then treat the two CYC packets as indicating an overflow. |
| Status | For the steppings affected, see the Summary Table of Changes. |

| | |
|--------------------|---|
| KBL042 | Last Level Cache Performance Monitoring Events May be Inaccurate |
| Problem | The performance monitoring events LONGEST_LAT_CACHE.REFERENCE (Event 2EH; Umask 4FH) and LONGEST_LAT_CACHE.MISS (Event 2EH; Umask 41H) count requests that reference or miss in the last level cache. However, due to this erratum, the count may be incorrect. |
| Implication | LONGEST_LAT_CACHE events may be incorrect. |
| Workaround | None identified. Software may use the following OFFCORE_REQUESTS model-specific sub events that provide related performance monitoring data: DEMAND_DATA_RD, DEMAND_CODE_RD, DEMAND_RFO, ALL_DATA_RD, L3_MISS_DEMAND_DATA_RD, ALL_REQUESTS. |
| Status | For the steppings affected, see the Summary Table of Changes. |

| | |
|--------------------|---|
| KBL043 | #GP Occurs Rather Than #DB on Code Page Split Inside an Intel® SGX Enclave |
| Problem | When executing within an Intel® SGX (Software Guard Extensions) enclave, a #GP (general-protection exception) may be delivered instead of a #DB (debug exception) when an instruction breakpoint is detected. This occurs when the instruction to be executed spans two pages, the second of which has an entry in the EPCM (enclave page cache map) that is not valid. |
| Implication | Debugging software may not be invoked when an instruction breakpoint is detected. |
| Workaround | Software should ensure that all pages containing enclave instructions have valid EPCM entries. |
| Status | For the steppings affected, see the Summary Table of Changes. |



| | |
|--------------------|---|
| KBL044 | Execution of VAESENCLAST Instruction May Produce a #NM Exception Instead of a #UD Exception |
| Problem | Execution of VAESENCLAST with VEX.L= 1 should signal a #UD (Invalid Opcode) exception, however, due to the erratum, a #NM (Device Not Available) exception may be signaled. |
| Implication | As a result of this erratum, an operating system may restore AVX and other state unnecessarily. |
| Workaround | None identified. |
| Status | For the steppings affected, see the Summary Table of Changes. |

| | |
|--------------------|---|
| KBL045 | Intel® SGX Enclave Accesses to the APIC-Access Page May Cause APIC-Access VM Exits |
| Problem | In VMX non-root operation, Intel SGX (Software Guard Extensions) enclave accesses to the APIC-access page may cause APIC-access VM exits instead of page faults. |
| Implication | A VMM (virtual-machine monitor) may receive a VM exit due to an access that should have caused a page fault, which would be handled by the guest OS (operating system). |
| Workaround | A VMM avoids this erratum if it does not map any part of the EPC (Enclave Page Cache) to the guest's APIC-access address; an operating system avoids this erratum if it does not attempt indirect enclave accesses to the APIC. |
| Status | For the steppings affected, see the Summary Table of Changes. |

| | |
|--------------------|---|
| KBL046 | CR3 Filtering Does Not Compare Bits [11:5] of CR3 and IA32_RTIT_CR3_MATCH in PAE Paging Mode |
| Problem | In PAE paging mode, the CR3[11:5] are used to locate the page-directory-pointer table. Due to this erratum, those bits of CR3 are not compared to IA32_RTIT_CR3_MATCH (MSR 572H) when IA32_RTIT_CTL.CR3Filter (MSR 570H, bit 7) is set. |
| Implication | If multiple page-directory-pointer tables are co-located within a 4KB region, CR3 filtering will not be able to distinguish between them so additional processes may be traced. |
| Workaround | None identified. |
| Status | For the steppings affected, see the Summary Table of Changes. |

| | |
|--------------------|--|
| KBL047 | x87 FDP Value May be Saved Incorrectly |
| Problem | Execution of the FSAVE, FNSAVE, FSTENV, or FNSTENV instructions in real-address mode or virtual-8086 mode may save an incorrect value for the x87 FDP (FPU data pointer). This erratum does not apply if the last non-control x87 instruction had an unmasked exception. |
| Implication | Software operating in real-address mode or virtual-8086 mode that depends on the FDP value for non-control x87 instructions without unmasked exceptions may not operate properly. |
| Workaround | None identified. Software should use the FDP value saved by the listed instructions only when the most recent non-control x87 instruction incurred an unmasked exception. |



| | |
|---------------|---|
| Status | For the steppings affected, see the Summary Table of Changes. |
|---------------|---|

| | |
|--------------------|---|
| KBL048 | PECI Frequency Limited to 1 MHz |
| Problem | The PECI (Platform Environmental Control Interface) 3.1 specification's operating frequency range is 0.2 MHz to 2 MHz. Due to this erratum, PECI may be unreliable when operated above 1 MHz. |
| Implication | Platforms attempting to run PECI above 1 MHz may not behave as expected. |
| Workaround | None identified. Platforms should limit PECI operating frequency to 1 MHz. |
| Status | For the steppings affected, see the Summary Table of Changes. |

| | |
|--------------------|--|
| KBL049 | Processor Graphics IOMMU Unit May Not Mask DMA Remapping Faults |
| Problem | Intel® Virtualization Technology for Directed I/O specification specifies setting the FPD (Fault Processing Disable) field in the context (or extended-context) entry of IOMMU to mask recording of qualified DMA remapping faults for DMA requests processed through that context entry. Due to this erratum, the IOMMU unit for Processor Graphics device may record DMA remapping faults from Processor Graphics device (Bus: 0; Device: 2; Function: 0) even when the FPD field is set to 1. |
| Implication | Software may continue to observe DMA remapping faults recorded in the IOMMU Fault Recording Register even after setting the FPD field. |
| Workaround | None identified. Software may mask the fault reporting event by setting the IM (Interrupt Mask) field in the IOMMU Fault Event Control register (Offset 038H in GFXVTBAR). |
| Status | For the steppings affected, see the Summary Table of Changes. |

| | |
|--------------------|---|
| KBL050 | Intel® PT CYCThresh Value of 13 is Not Supported |
| Problem | Intel PT (Intel® Processor Trace) CYC (Cycle Count) threshold is configured through CYCThresh field in bits [22:19] of IA32_RTIT_CTL MSR (570H). A value of 13 is advertised as supported by CPUID (leaf 14H, sub-lead 1H). Due to this erratum, if CYCThresh is set to 13 then the CYC threshold will be 0 cycles instead of 4096 (2 ¹³ -1) cycles. |
| Implication | CYC packets may be issued in higher rate than expected if threshold value of 13 is used. |
| Workaround | None identified. Software should not use value of 13 for CYC threshold. |
| Status | For the steppings affected, see the Summary Table of Changes. |

| | |
|--------------------|--|
| KBL051 | Enabling VMX-Preemption Timer Blocks HDC Operation |
| Problem | HDC (Hardware Duty Cycling) will not put the physical package into the forced idle state while any logical processor is in VMX non-root operation and the "activate VMX-preemption timer" VM-execution control is 1. |
| Implication | HDC will not provide the desired power reduction when the VMX-preemption timer is active in VMX non-root operation. |
| Workaround | None identified. |
| Status | For the steppings affected, see the Summary Table of Changes. |



| | |
|--------------------|--|
| KBL052 | Integrated Audio Codec May Not be Detected |
| Problem | Integrated Audio Codec may lose power when LPSP (Low-Power Single Pipe) mode is enabled for an eDP* (embedded DisplayPort) or DP/HDMI ports. Platforms with Intel® SST (Intel® Smart Sound Technology) enabled are not affected. |
| Implication | The Audio Bus driver may attempt to do enumeration of Codecs when eDP or DP/HDMI port enters LPSP mode, due to this erratum, the Integrated Audio Codec will not be detected and audio maybe be lost. |
| Workaround | Intel® Graphics Driver 15.40.11.4312 or later will prevent the Integrated Audio Codec from losing power when LPSP mode is enabled. |
| Status | For the steppings affected, see the Summary Table of Changes. |

| | |
|--------------------|---|
| KBL053 | Display Flickering May be Observed with Specific eDP Panels |
| Problem | The processor may incorrectly configure transmitter buffer characteristics if the associated eDP panel requests VESA equalization preset 3, 5, 6, or 8. |
| Implication | Display flickering or display loss maybe observed. |
| Workaround | Intel® Graphics Driver version 15.40.12.4326 or later contains a workaround for this erratum. |
| Status | For the steppings affected, see the Summary Table of Changes. |

| | |
|--------------------|--|
| KBL054 | Incorrect Branch Predicted Bit in BTS/BTM Branch Records |
| Problem | BTS (Branch Trace Store) and BTM (Branch Trace Message) send branch records to the Debug Store management area and system bus respectively. The Branch Predicted bit (bit 4 of eighth byte in BTS/BTM records) should report whether the most recent branch was predicted correctly. Due to this erratum, the Branch Predicted bit may be incorrect. |
| Implication | BTS and BTM cannot be used to determine the accuracy of branch prediction. |
| Workaround | None identified. |
| Status | For the steppings affected, see the Summary Table of Changes. |

| | |
|--------------------|--|
| KBL055 | MACHINE_CLEARS.MEMORY_ORDERING Performance Monitoring Event May Undercount |
| Problem | The performance monitoring event MACHINE_CLEARS.MEMORY_ORDERING (Event C3H; Umask 02H) counts the number of machine clears caused by memory ordering conflicts. However due to this erratum, this event may undercount for VGATHER*/VPGATHER* instructions of four or more elements. |
| Implication | MACHINE_CLEARS.MEMORY_ORDERING performance monitoring event may undercount. |
| Workaround | None identified. |
| Status | For the steppings affected, see the Summary Table of Changes. |



| | |
|--------------------|--|
| KBL056 | CTR_FRZ May Not Freeze Some Counters |
| Problem | IA32_PERF_GLOBAL_STATUS.CTR_FRZ (MSR 38EH, bit 59) is set when either (1) IA32_DEBUGCTL.FREEZE_PERFMON_ON_PMI (MSR 1D9H, bit 12) is set and a PMI is triggered, or (2) software sets bit 59 of IA32_PERF_GLOBAL_STATUS_SET (MSR 391H). When set, CTR_FRZ should stop all core performance monitoring counters from counting. However, due to this erratum, IA32_PMC4-7 (MSR C5-C8H) may not stop counting. IA32_PMC4-7 are only available when a processor core is not shared by two logical processors. |
| Implication | General performance monitoring counters 4-7 may not freeze when IA32_PERF_GLOBAL_STATUS.CTR_FRZ is set. |
| Workaround | None identified. |
| Status | For the steppings affected, see the Summary Table of Changes. |

| | |
|--------------------|--|
| KBL057 | Instructions And Branches Retired Performance Monitoring Events May Overcount |
| Problem | The performance monitoring events INST_RETIRE (Event C0H; any Umask value) and BR_INST_RETIRE (Event C4H; any Umask value) count instructions retired and branches retired, respectively. However, due to this erratum, these events may overcount in certain conditions when: <ul style="list-style-type: none">- Executing VMASKMOV* instructions with at least one masked vector element- Executing REP MOVS or REP STOS with Fast Strings enabled (IA32_MISC_ENABLE MSR (1A0H), bit 0 set)- An MPX #BR exception occurred on BNDLDX/BNDSTX instructions and the BR_INST_RETIRE (Event C4H; Umask is 00H or 04H) is used. |
| Implication | INST_RETIRE and BR_INST_RETIRE performance monitoring events may overcount. |
| Workaround | None identified. |
| Status | For the steppings affected, see the Summary Table of Changes. |

| | |
|--------------------|--|
| KBL058 | Some OFFCORE_RESPONSE Performance Monitoring Events May Overcount |
| Problem | The performance monitoring events OFFCORE_RESPONSE (Events B7H and BBH) should count off-core responses matching the request-response configuration specified in MSR_OFFCORE_RSP_0 and MSR_OFFCORE_RSP_1 (1A6H and 1A7H, respectively) for core-originated requests. However, due to this erratum, DMND_RFO (bit 1), DMND_IFETCH (bit 2) and OTHER (bit 15) request types may overcount. |
| Implication | Some OFFCORE_RESPONSE events may overcount. |
| Workaround | None identified. Software may use the following model-specific events that provide related performance monitoring data: OFFCORE_REQUESTS (all sub-events), L2_TRANS.L2_WB and L2_RQSTS.PF_MISS. |
| Status | For the steppings affected, see the Summary Table of Changes. |



| | |
|--------------------|---|
| KBL059 | Instructions Fetch #GP After RSM During Inter® PT May Push Incorrect RFLAGS Value on Stack |
| Problem | If Intel PT (Processor Trace) is enabled, a #GP (General Protection Fault) caused by the instruction fetch immediately following execution of an RSM instruction may push an incorrect value for RFLAGS onto the stack. |
| Implication | Software that relies on RFLAGS value pushed on the stack under the conditions described may not work properly. |
| Workaround | None identified. |
| Status | For the steppings affected, see the Summary Table of Changes. |

| | |
|--------------------|---|
| KBL060 | Access to SGX EPC Page in BLOCKED State is Not Reported as an SGX-Induced Page Fault |
| Problem | If a page fault results from attempting to access a page in the SGX (Intel® Software Guard Extensions) EPC (Enclave Page Cache) that is in the BLOCKED state, the processor does not set bit 15 of the error code and thus fails to indicate that the page fault was SGX-induced. |
| Implication | Due to this erratum, software may not recognize these page faults as being SGX-induced. |
| Workaround | Before using the EBLOCK instruction to marking a page as BLOCKED, software should use paging to mark the page not present. |
| Status | For the steppings affected, see the Summary Table of Changes. |

| | |
|--------------------|---|
| KBL061 | MTF VM Exit on XBEGIN Instruction May Save State Incorrectly |
| Problem | Execution of an XBEGIN instruction while the monitor trap flag VM-execution control is 1 will be immediately followed by an MTF VM exit. If advanced debugging of RTM transactional regions has been enabled, the VM exit will erroneously save as instruction pointer the address of the XBEGIN instruction instead of the fallback instruction address specified by the XBEGIN instruction. In addition, it will erroneously set bit 16 of the pending-debug-exceptions field in the VMCS indicating that a debug exception or a breakpoint exception occurred. |
| Implication | Software using the monitor trap flag to debug or trace transactional regions may not operate properly. Intel has not observed this erratum with any commercially available software. |
| Workaround | None identified |
| Status | For the steppings affected, see the Summary Table of Changes. |

| | |
|--------------------|---|
| KBL062 | Intel® Turbo Boost Technology May be Incorrectly Reported as Supported on Intel® Core™ i3 U/H/S, Select Intel® Mobile Pentium®, Intel® Mobile Celeron®, Intel® Pentium® and Intel® Celeron® Processors |
| Problem | These processors may incorrectly report support for Intel® Turbo Boost Technology via CPUID.06H.EAX bit 1. |
| Implication | The CPUID instruction may report Turbo Boost Technology as supported even though the processor does not permit operation above the Base Frequency. |
| Workaround | None identified. |
| Status | For the steppings affected, see the Summary Table of Changes. |



| | |
|--------------------|--|
| KBL063 | Performance Monitoring Counters May Undercount When Using CPL Filtering |
| Problem | Performance Monitoring counters configured to count only OS or only USR events by setting exactly one of bits 16 or 17 in IA32_PERFEVTSELx MSRs (186H-18DH) may not count for a brief period during the transition to a new CPL. |
| Implication | A measurement of ring transitions (using the edge-detect bit 18 in IA32_PERFEVTSELx) may undercount, such as CPL_CYCLES.RINGO_TRANS (Event 5CH, Umask 01H). Additionally, the sum of an OS-only event and a USR-only event may not exactly equal an event counting both OS and USR. Intel has not observed any other software-visible impact |
| Workaround | None identified. |
| Status | For the steppings affected, see the Summary Table of Changes. |

| | |
|--------------------|--|
| KBL064 | Executing a 256 Bit AVX Instruction May Cause Unpredictable Behavior |
| Problem | Under complex micro-architectural conditions, executing a 256 AVX bit instruction may result in unpredictable system behavior. |
| Implication | When this erratum occurs, the system may behave unpredictably. |
| Workaround | It is possible for the BIOS to contain a workaround for this erratum. |
| Status | For the steppings affected, see the Summary Table of Changes. |

| | |
|--------------------|--|
| KBL065 | System May Hang During Display Power Cycles |
| Problem | When the display is turned on after being shutoff to save power or when the display is exiting PSR (Panel Self Refresh) mode, the system may hang. |
| Implication | When this erratum occurs the system may hang. |
| Workaround | It is possible for the BIOS to contain a workaround for this erratum. |
| Status | For the steppings affected, see the Summary Table of Changes. |

| | |
|--------------------|---|
| KBL066 | Certain Non-Canonical IA32_BNDCFGS Values Will Not Cause VM-Entry Failures |
| Problem | If the VM-entry controls Load IA32_BNDCFGS field (bit 16) is 1, VM-entry should fail when the value of the guest IA32_BNDCFGS field in the VMCS is not canonical (that is, when bits 63:47 are not identical). Due to this erratum, VM-entry does not fail if bits 63:48 are identical but differ from bit 47. In this case, VM-entry loads the IA32_BNDCFGS MSR with a value in which bits 63:48 are identical to the value of bit 47 in the VMCS field. |
| Implication | If the value of the guest IA32_BNDCFGS field in the VMCS is not canonical, VM-entry may load the IA32_BNDCFGS MSR with a value different from that of the VMCS field. |
| Workaround | None identified. |
| Status | For the steppings affected, see the Summary Table of Changes. |



| | |
|--------------------|--|
| KBL067 | PEBS EventingIP Field May Be Incorrect Under Certain Conditions |
| Problem | The EventingIP field in the PEBS (Processor Event-Based Sampling) record reports the address of the instruction that triggered the PEBS event. Under certain complex microarchitectural conditions, the EventingIP field may be incorrect. |
| Implication | When this erratum occurs, performance monitoring software may not attribute the PEBS events to the correct instruction. |
| Workaround | None identified. |
| Status | For the steppings affected, see the Summary Table of Changes. |

| | |
|--------------------|---|
| KBL068 | HWP's Guaranteed_Performance Updated Only on Configurable TDP Changes |
| Problem | According to HWP (Hardware P-states) specification, the Guaranteed_Performance field (bits[15:8]) in the IA32_HWP_CAPABILITIES MSR (771H) should be updated as a result of changes in the configuration of TDP, RAPL (Running Average Power Limit), and other platform tuning options that may have dynamic effects on the actual guaranteed performance support level. Due to this erratum, the processor will update the Guaranteed_Performance field only as a result of configurable TDP dynamic changes. |
| Implication | Software may read a stale value of the Guaranteed_Performance field. |
| Workaround | None identified. |
| Status | For the steppings affected, see the Summary Table of Changes. |

| | |
|--------------------|---|
| KBL069 | RF May be Incorrectly Set in The EFLAGS That is Saved on a Fault in PEBS or BTS |
| Problem | After a fault due to a failed PEBS (Processor Event Based Sampling) or BTS (Branch Trace Store) address translation, the RF (resume flag) may be incorrectly set in the EFLAGS image that is saved. |
| Implication | When this erratum occurs, a code breakpoint on the instruction following the return from handling the fault will not be detected. This erratum only happens when the user does not prevent faults on PEBS or BTS. |
| Workaround | Software should always prevent faults on PEBS or BTS. |
| Status | For the steppings affected, see the Summary Table of Changes. |

| | |
|--------------------|---|
| KBL070 | Intel® PT ToPA PMI Does Not Freeze Performance Monitoring Counters |
| Problem | Due to this erratum, if IA32_DEBUGCTL.FREEZE_PERFMON_ON_PMI (MSR 1D9H, bit 12) is set to 1 when Intel PT (Processor Trace) triggers a ToPA (Table of Physical Addresses) PMI (PerfMon Interrupt), performance monitoring counters are not frozen as expected. |
| Implication | Performance monitoring counters will continue to count for events that occur during PMI handler execution. |
| Workaround | PMI handler software can programmatically stop performance monitoring counters upon entry. |
| Status | For the steppings affected, see the Summary Table of Changes. |



| | |
|--------------------|--|
| KBL071 | HWP's Maximum_Performance Value is Reset to 0xFF |
| Problem | According to HWP (Hardware P-states) specification, the reset value of the Maximum_Performance field (bits [15:8]) in IA32_HWP_REQUEST MSR (774h) should be set to the value of IA32_HWP_CAPABILITIES MSR (771H) Highest_Performance field (bits[7:0]) after reset. Due to this erratum, the reset value of Maximum_Performance is always set to 0xFF. |
| Implication | Software may see an unexpected value in Maximum Performance field. Hardware clipping will prevent invalid performance states. |
| Workaround | None identified. |
| Status | For the steppings affected, see the Summary Table of Changes. |

| | |
|--------------------|---|
| KBL072 | HWP's Guaranteed_Performance and Relevant Status/Interrupt May be Updated More Than Once Per Second |
| Problem | According to HWP (Hardware P-states) specification, the Guaranteed_Performance field (bits[15:8]) in the IA32_HWP_CAPABILITIES MSR (771H) and the Guaranteed_Performance_Change (bit 0) bit in IA32_HWP_STATUS MSR (777H) should not be changed more than once per second nor should the thermal interrupt associated with the change to these fields be signaled more than once per second. Due to this erratum, the processor may change these fields and generate the associated interrupt more than once per second |
| Implication | HWP interrupt rate due to Guaranteed_Performance field change can be higher than specified |
| Workaround | Clearing the Guaranteed_Performance_Change status bit no more than once per second will ensure that interrupts are not generated at too fast a rate |
| Status | For the steppings affected, see the Summary Table of Changes. |

| | |
|----------------|--|
| KBL073 | Some Memory Performance Monitoring Events May Produce Incorrect Results When Filtering on Either OS or USR Modes |
| Problem | <p>The memory at-retirement performance monitoring events (listed below) may produce incorrect results when a performance counter is configured in OS-only or USR-only modes (bits 17 or 16 in IA32_PERFVTSELx MSR). Counters with both OS and USR bits set are not affected by this erratum.</p> <p>The list of affected memory at-retirement events is as follows:</p> <ul style="list-style-type: none"> MEM_INST_RETIRED.STLB_MISS_LOADS event D0H, umask 11H MEM_INST_RETIRED.STLB_MISS_STORES event D0H, umask 12H MEM_INST_RETIRED.LOCK_LOADS event D0H, umask 21H MEM_INST_RETIRED.SPLIT_LOADS event D0H, umask 41H MEM_INST_RETIRED.SPLIT_STORES event D0H, umask 42H MEM_LOAD_RETIRED.L2_HIT event D1H, umask 02H MEM_LOAD_RETIRED.L3_HIT event D1H, umask 04H MEM_LOAD_RETIRED.L4_HIT event D1H, umask 80H MEM_LOAD_RETIRED.L1_MISS event D1H, umask 08H MEM_LOAD_RETIRED.L2_MISS event D1H, umask 10H MEM_LOAD_RETIRED.L3_MISS event D1H, umask 20H MEM_LOAD_RETIRED.FB_HIT event D1H, umask 40H |



| | |
|--------------------|---|
| | MEM_LOAD_L3_HIT_RETIRED.XSNP_MISS event D2H, umask 01H MEM_LOAD_L3_HIT_RETIRED.XSNP_HIT event D2H, umask 02H MEM_LOAD_L3_HIT_RETIRED.XSNP_HITM event D2H, umask 04H MEM_LOAD_L3_HIT_RETIRED.XSNP_NONE event D2H, umask 08H |
| Implication | The listed performance monitoring events may produce incorrect results including PEBS records generated at an incorrect point |
| Workaround | None identified |
| Status | For the steppings affected, see the Summary Table of Changes. |

| | |
|--------------------|---|
| KBL074 | HWP May Generate Thermal Interrupt While Not Enabled |
| Problem | Due to this erratum, the conditions for HWP (Hardware P-states) to generate a thermal interrupt on a logical processor may generate thermal interrupts on both logical processors of that core. |
| Implication | If two logical processors of a core have different configurations of HWP (e.g. only enabled on one), an unexpected thermal interrupt may occur on one logical processor due to the HWP settings of the other logical processor. |
| Workaround | Software should configure HWP consistently on all logical processors of a core. |
| Status | For the steppings affected, see the Summary Table of Changes. |

| | |
|--------------------|--|
| KBL075 | Camera Device Does Not Issue an MSI When INTx is Enabled |
| Problem | When both MSI (Message Signaled Interrupts) and legacy INTx are enabled by the camera device, INTx is asserted rather than issuing the MSI, in violation of the PCI Local Bus Specification. |
| Implication | Due to this erratum, camera device interrupts can be lost leading to device failure. |
| Workaround | The camera device must disable legacy INTx by setting bit 10 of PCICMD (Bus 0; Device 5; Function 0; Offset 04H) before MSI is enabled |
| Status | For the steppings affected, see the Summary Table of Changes. |

| | |
|--------------------|---|
| KBL076 | An x87 Store Instruction Which Pends #PE May Lead to Unexpected Behavior When EPT A/D is Enabled. |
| Problem | An x87 store instruction which causes a #PE (Precision Exception) to be pended and updates an EPT (Extended Page Tables) A/D bit may lead to unexpected behavior. |
| Implication | The VMM may experience unexpected x87 fault or a machine check exception with the value of 0x150 in IA32_MCO_STATUS.MCACOD (bits [15:0] in MSR 401H) |
| Workaround | It is possible for the BIOS to contain a workaround for this erratum |
| Status | For the steppings affected, see the Summary Table of Changes. |

| | |
|----------------|--|
| KBL077 | Use of VMASKMOV to Store When Using EPT May Fail |
| Problem | Use of VMASKMOV instructions to store data that splits over two pages, when the instruction resides on the first page may cause a hang if EPT (Extended Page Tables) is in use, and the store to the second page requires setting the A/D bits in the EPT entry. |



| | |
|--------------------|---|
| Implication | Due to this erratum, the CPU may hang on the execution of VMASKMOV |
| Workaround | It is possible for the BIOS to contain a workaround for this erratum. |
| Status | For the steppings affected, see the Summary Table of Changes. |

| | |
|--------------------|---|
| KBL078 | PECI May Not be Functional After Package C10 Resume |
| Problem | When resuming from Package C10, Peci may fail to function properly. |
| Implication | When this erratum occurs, the Peci does not respond to any command. |
| Workaround | It is possible for the BIOS to contain a workaround for this erratum. |
| Status | For the steppings affected, see the Summary Table of Changes. |

| | |
|--------------------|--|
| KBL079 | Attempts to Retrain a PCIe* Link May be Ignored |
| Problem | A PCIe link should retrain when Retrain Link (bit 5) in the Link Control register (Bus 0; Device 1; Functions 0,1,2; Offset 0xB0) is set. Due to this erratum, if the link is in the L1 state, it may ignore the retrain request |
| Implication | The PCIe link may not behave as expected. |
| Workaround | It is possible for the BIOS to contain a workaround for this erratum. |
| Status | For the steppings affected, see the Summary Table of Changes. |

| | |
|--------------------|--|
| KBL080 | PCIe* Expansion ROM Base Address Register May be Incorrect |
| Problem | After PCIe 8.0 GT/s Link Equalization on a root port (Bus 0; Device 1; Function 0, 1, 2) has completed, the Expansion ROM Base Address Register (Offset 38H) may be incorrect. |
| Implication | Software that uses this BAR may behave unexpectedly. Intel has not observed this erratum with any commercially available software. |
| Workaround | None identified |
| Status | For the steppings affected, see the Summary Table of Changes. |

| | |
|--------------------|---|
| KBL081 | PCIe* Port Does Not Support DLL Link Activity Reporting |
| Problem | The PCIe Base specification requires DLL (Data Link Layer) Link Activity Reporting when 8 GT/s link speed is supported. Due to this erratum, link activity reporting is not supported |
| Implication | Due to this erratum, PCIe port does not support DLL Link Activity Reporting when 8 GT/s is supported. |
| Workaround | None identified |
| Status | For the steppings affected, see the Summary Table of Changes. |



| | |
|--------------------|--|
| KBL082 | BNDLDX And BNDSTX May Not Signal #GP on Non-Canonical Bound Directory Access |
| Problem | BNDLDX and BNDSTX instructions access the bound's directory and table to load or store bounds. These accesses should signal #GP (general protection exception) when the address is not canonical (i.e. bits 48 to 63 are not the sign extension of bit 47). Due to this erratum, #GP may not be generated by the processor when a non-canonical address is used by BNDLDX or BNDSTX for their bound directory memory access. |
| Implication | Intel has not observed this erratum with any commercially available software. |
| Workaround | Software should use canonical addresses for bound directory accesses. |
| Status | For the steppings affected, see the Summary Table of Changes. |

| | |
|--------------------|---|
| SKL0083 | RING_PERF_LIMIT_REASONS May be Incorrect |
| Problem | Under certain conditions, RING_PERF_LIMIT_REASONS (MSR 6B1H) may incorrectly assert the OTHER status bit (bit 8) as well as the OTHER log bit (bit 24). |
| Implication | When this erratum occurs, software using this register will incorrectly report clipping because of the OTHER reason. |
| Workaround | It is possible for the BIOS to contain a workaround for this erratum. |
| Status | For the steppings affected, see the Summary Table of Changes. |

| | |
|--------------------|--|
| KBL084 | Processor May Exceed VCCCore ICCMAX During Multi-core Turbo |
| Problem | Due to this erratum, the maximum ring frequency limit is incorrectly configured to be 100MHz higher than intended. |
| Implication | VCCCore ICCMAX may be temporarily exceeded when all the cores are executing at a Turbo frequency. |
| Workaround | It is possible for the BIOS to contain a workaround for this erratum. |
| Status | For the steppings affected, see the Summary Table of Changes. |

| | |
|--------------------|--|
| KBL085 | Performance Monitoring Load Latency Events May Be Inaccurate For Gather Instructions |
| Problem | The performance monitoring events MEM_TRANS_RETIRED.LOAD_LATENCY_* (Event CDH; UMask 01H; any latency) count load instructions whose latency exceed a predefined threshold, where the loads are randomly selected using the load latency facility (an extension of PEBS). However due to this erratum, these events may count incorrectly for VGATHER*/VPGATHER* instructions. |
| Implication | The Load Latency Performance Monitoring events may be Inaccurate for Gather instructions. |
| Workaround | None identified |
| Status | For the steppings affected, see the Summary Table of Changes. |



| | |
|--------------------|---|
| KBL086 | EDRAM Corrected Error Events May Not be Properly Logged After a Warm Reset |
| Problem | After a warm reset, an EDRAM corrected error may not be logged correctly until the associated machine check register is initialized. This erratum may affect IA32_MC8_STATUS or IA32_MC10_STATUS. |
| Implication | The EDRAM corrected error information may be lost when this erratum occurs. |
| Workaround | Data from the affected machine check registers should be read and the registers initialized as soon as practical after a warm reset. |
| Status | For the steppings affected, see the Summary Table of Changes. |

| | |
|--------------------|---|
| KBL087 | Unpredictable System Behavior May Occur When System Agent Enhanced Intel® Speedstep® is Enabled |
| Problem | Under complex system conditions, SA-GV (System Agent Enhanced Intel® Speedstep®) may result in unpredictable system behavior. |
| Implication | When this erratum occurs, the system may behave unpredictably. |
| Workaround | It is possible for the BIOS to contain a workaround for this erratum. |
| Status | For the steppings affected, see the Summary Table of Changes. |

| | |
|--------------------|---|
| KBL088 | Processor May Hang Under Complex Scenarios |
| Problem | Under a complex micro-architectural conditions, the processor may hang with an internal timeout error (MCACOD 0400H) logged into IA32_MCi_STATUS. |
| Implication | This erratum may result in a processor hang. |
| Workaround | It is possible for the BIOS to contain a workaround for this erratum. |
| Status | For the steppings affected, see the Summary Table of Changes. |

| | |
|--------------------|---|
| KBL089 | Some Bits in MSR_MISC_PWR_MGMT May be Updated on Writing Illegal Values to This MSR |
| Problem | Attempts to write illegal values to MSR_MISC_PWR_MGMT (MSR 0x1AA) result in #GP (General Protection Fault) and should not change the MSR value. Due to this erratum, some bits in the MSR may be updated on writing an illegal value. |
| Implication | Certain fields may be updated with allowed values when writing illegal values to MSR_MISC_PWR_MGMT. Such writes will always result in #GP as expected. |
| Workaround | None identified. Software should not attempt to write illegal values to this MSR. |
| Status | For the steppings affected, see the Summary Table of Changes. |

| | |
|----------------|---|
| KBL090 | Violations of Intel® Software Guard Extensions (Intel® SGX) Access-Control Requirements Produce #GP Instead of #PF |
| Problem | Intel® Software Guard Extensions (Intel® SGX) define new access-control requirements on memory accesses. A violation of any of these requirements causes a page fault (#PF) that sets bit 15 (SGX) in the page-fault error code. Due to this erratum, these violations instead cause general-protection exceptions (#GP). |



| | |
|--------------------|---|
| Implication | Software resuming from system sleep states S3 or S4 and relying on receiving a page fault from the above enclave accesses may not operate properly. |
| Workaround | Software can monitor #GP faults to detect that an enclave has been destroyed and needs to be rebuilt after resuming from S3 or S4 |
| Status | For the steppings affected, see the Summary Table of Changes. |

| | |
|--------------------|---|
| KBL091 | IA32_RTIT_CR3_MATCH MSR Bits[11:5] Are Treated As Reserved |
| Problem | Due to this erratum, bits[11:5] in IA32_RTIT_CR3_MATCH (MSR 572H) are reserved; an MSR write that attempts to set that field to a non-zero value will result in a #GP fault. |
| Implication | The inability to write the identified bit field does not affect the functioning of Intel® PT (Intel® Processor Trace) operation because, as described in erratum SKL061, the bit field that is the subject of this erratum is not used during Intel PT CR3 filtering. |
| Workaround | Ensure that bits 11:5 of the value written to IA32_RTIT_CR3_MATCH are zero, including cases where the selected page-directory-pointer-table base address has non-zero bits in this range. |
| Status | For the steppings affected, see the Summary Table of Changes. |

| | |
|--------------------|---|
| KBL092 | APIC Timer Interrupt May Not be Generated at The Correct Time In TSC-Deadline Mode |
| Problem | After writing to the IA32_TSC_ADJUST MSR (3BH), any subsequent write to the IA32_TSC_DEADLINE MSR (6E0H) may incorrectly process the desired deadline. When this erratum occurs, the resulting timer interrupt may be generated at the incorrect time. |
| Implication | When the local APIC (Advanced Programmable Interrupt Controller) timer is configured for TSC-Deadline mode, a timer interrupt may be generated much earlier than expected or much later than expected. Intel has not observed this erratum with most commercially available software. |
| Workaround | It is possible for the BIOS to contain a workaround for this erratum. |
| Status | For the steppings affected, see the Summary Table of Changes. |

| | |
|--------------------|---|
| KBL093 | The Intel PT CR3 Filter is Not Re-evaluated on VM Entry |
| Problem | On a VMRESUME or VMLAUNCH with both TraceEn[0] and CR3Filter[7] in IA32_RTIT_CTL (MSR 0570H) set to 1 both before the VM Entry and after, the new value of CR3 is not compared with IA32_RTIT_CR3_MATCH (MSR 0572H). |
| Implication | The Intel PT (Processor Trace) CR3 filtering mechanism may continue to generate packets despite a mismatching CR3 value, or may fail to generate packets despite a matching CR3, as a result of an incorrect value of IA32_RTIT_STATUS.ContextEn[1] (MSR 0571H) that results from the failure to re-evaluate the CR3 match on VM entry. |
| Workaround | None identified. |
| Status | For the steppings affected, see the Summary Table of Changes. |



| | |
|--------------------|---|
| KBL094 | Display Slowness May be Observed Under Certain Display Commands Scenario |
| Problem | Back to back access to the VGA register ports (I/O addresses 0x3C2, 0x3CE, 0x3CF) will experience higher than expected latency. |
| Implication | Due to this erratum, the processor may redraw the slowly when in VGA mode. |
| Workaround | None identified. |
| Status | For the steppings affected, see the Summary Table of Changes. |

§



Specification Changes

There are no Specification Changes in this Specification Update revision.

§



Specification Clarifications

There are no specification clarifications in this Specification Update revision.

§



Documentation Changes

There are no documentation changes in this Specification Update revision.

§